25121

REPORT of SURVEY for REPAIRS.

No. 569 Survey held at London Date Nov to Dec 30th 1862

on the Ship "Anglesey" Master Smith

Tonnage 965 / 1018 Built at London When built 1832

By whom built Owners R. Green

Port belonging to London Destined Voyage Melbourne

If Surveyed Afloat or in Dry Dock Messrs Greens' Dry Dock & E. I. Dock -

Last Survey, No. 24409 Port London Classed 13 A 1.

REPAIRS Now done, the Yellow Metal Sheathing renewed on Felt, the Ship hung in Shores and Caulked from the Keel to the top of the Wales, the butts of the topsides, the middle line and butts of the upper deck and the upper deck waterway - The Rudder Braces taken off, Caulked in way of, and refitted - the Poop deck Caulked, and a portion of the inside poop drift renewed - the seams of the bottom Spunyarned -

Present Condition of the

Decks	Part Caulked	Treenails	Good where seen	Windlass and Capstan	Good and sufficient
Waterways	Caulked	Breasthooks and Stemson		Pumps	
Comings	Good	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	firm	Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers	Butts Caulked	Clamps and Shelfs		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	Caulked	~~Copper~~ Yellow Metal on Felt When put on	Now	Standing & Running Rigging	
Plank (Bottom) and Counter	Caulked				

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where tested -

She is now in good and Efficient Condition, fit in my opinion to remain as classed 13 A 1.

B. Waymouth

The Amount of Fee ..... £ — : — : — is received by me,

Special ..... 1 : 1 : —

Certificate (if required) — : 5 : —

Committee's Minute 9th January 1863

Character assigned 13 A 1 = record

Charge £1.1.0

Certificate to Blackwall

© 2019 Lloyd's Register Foundation

LON646-0295