25562

ANNUAL SURVEYS.

No. 244 Survey held at London Date May to June 4th 1863

on the Ship "Glen Gairn" Master W. S. Garrick

Tonnage 894 Built at Aberdeen When built 1863

By whom built Owners Nicol

Port belonging to Aberdeen Destined Voyage Australia

If Surveyed Afloat or in Dry Dock Canal Dry Dock -

Last Survey, No. 2108 Port of Aberdeen Classed 9 A 1. 63

The present Condition of the

Decks, Waterways, Comings: Good

Upper Deck Beams & Fastenings, Lower Deck Beams & Fastenings: Firm

Plankshеers, Sheerstrakes, Topsides, Wales: Good

Plank (Bottom) and Counter: Good

Treenails, Breasthooks and Stemson, Transoms, Pointers, and Crutches, Timbers of the Frame at the Openings, Do Do at other places, Keelsons, Clamps and Shelfs, Ceiling, Rudder: Good

Copper: Yellow metal on Felt When put on: Now

Windlass and Capstan, Pumps, Boats, Masts, Yards, &c., Sails: Good and sufficient

Anchors No. of, Cables, Hawsers and Warps, Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways: Good where tested

Now done her bottom tested and the Caulking found good - Sheathed with Yellow Metal on Felt - She is fit in my opinion to remain as classed 9 A 1.

Committee's Minute 21st July 1863

Character assigned 9 A 1

B. Waymouth

Certificate (if required)

No. 414 Survey held at London Date June to July 9th 1863 -

on the Barque "Bride" Master Gibson

Tonnage 474 ~~554~~ Built at Sunderland When built 1851

By whom built Owners Messrs Temperley

Port belonging to London Destined Voyage New Zealand

If Surveyed Afloat or in Dry Dock Union Dry Dock & London Dock

Last Survey, No. 7350 Port of Sunderland Classed Cont 62 - 4 A 1. 62

The present Condition of the

Decks, Waterways, Comings: Good where seen

Upper Deck Beams & Fastenings, Lower Deck Beams & Fastenings: Firm

Plankshеers, Sheerstrakes, Topsides, Wales: Good where seen

Plank (Bottom) and Counter

Treenails, Breasthooks and Stemson, Transoms, Pointers, and Crutches, Timbers of the Frame at the Openings, Do Do at other places, Keelsons, Clamps and Shelfs, Ceiling, Rudder: Good where seen

Copper: Yellow metal on Felt When put on: 1862

Windlass and Capstan, Pumps, Boats, Masts, Yards, &c., Sails: Good and sufficient

Anchors No. of, Cables, Hawsers and Warps, Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways: Good where seen

Now done her Yellow Metal Sheathed - She is in good and efficient Condition, fit in my opinion to remain as classed Continued 4 A 1.

Committee's Minute 21st July 1863

Character assigned Cont 4 A 1

B. Waymouth

Certificate (if required).

© 2021 Lloyd's Register Foundation
LON647-0243