25581

ANNUAL SURVEYS.

Rec 24/7/63

No. 842 Survey held at London Date June 3rd 1863

on the Ship "Surrey" Master S. Durrant

Tonnage 1089 Built at Shields When built 1857

By whom built — Owners Messrs Marshall &

Port belonging to London Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock Messrs Jones Dry Dock

Last Survey, No. 24479 Port of London. Classed 13 A 1. 62

The present Condition of the

Decks	Caulked	Treenails		Windlass and Capstan	
Waterways	Caulked	Breasthooks and Stemson		Pumps	Good and sufficient
Comings	Good	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	Good	Timbers of the Frame	Good where seen	Masts, Yards, &c.	New main mast
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelfs		Anchors No. of	Good and sufficient
Sheerstrakes	Good where seen	Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper or Yellow Metal	Yellow Metal	Standing & Running Rigging	New fore & main riggings
Plank (Bottom) and Counter	Good	When put on	1862		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen

Now done her decks Caulked, main mast and her fore and main riggings renewed - Her Bower Anchors and Cables tested to the Admiralty proof - She is now in good and efficient Condition, fit in my opinion to remain as classed 13 A 1.

Committee's Minute 24 July 1863 B. Waymouth

Character assigned 13 A 1 WMA

(A+C.P) See Owner's letter - with Lon 24773 Certificate (if required)

No. 318 Survey held at London Date June 19th to July 9th 1863.

on the Ship "Pleasfordshire" Master J. C. Walker

Tonnage 1337 4 Built at Bombay When built 1853

By whom built — Owners G. Marshall

Port belonging to London Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock Canal Dry Dock & London Dock

Last Survey, No. 24459 Port of London Classed 6 mos * SS 5-7. A 1 2,62

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	Good where seen	Breasthooks and Stemson		Pumps	Good and sufficient
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	Seen	Timbers of the Frame	Good where seen	Masts, Yards, &c. and Set from	New Bowsprit
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelfs		Anchors No. of	Good and sufficient
Sheerstrakes	Caulking found caulked	Ceiling		Cables 30 Fath	
Topsides	Part Caulked	Rudder	Reduced in the heel	Hawsers and Warps	
Wales		Copper or Yellow Metal	Yellow Metal	Standing & Running Rigging	
Plank (Bottom) and Counter		When put on	1862 -		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen

From documents produced it appears that the wood sheathing on the bottom and the Yellow Metal sheathing was all renewed upon Felt in Bombay in September 1862 - Now done the Bowsprit Jibboom and a portion of the Riggings renewed, double topsail yards fitted with fore and drain topsails new - She is now fit in my opinion for the safe Conveyance of dry and perishable Cargoes to and from all parts of the world and to remain classed * A 1 - Asterisk

Committee's Minute 24th July 1863

Character assigned A 1 asterisk

(A+C.P) WMA B. Waymouth Certificate (if required).

© 2021 Lloyd's Register Foundation
LON647-0260