25760

REPORT of SURVEY for REPAIRS.

No. 886 Survey held at London Date Aug 19th to 26th 1863

on the Bk "Swanley" Master

Tonnage 350 390 Built at Sunderland When built 1853

By whom built Owners Messrs J. Shepherd &

Port belonging to London Destined Voyage not fixed

If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 24725 Port London Classed 13 A.1. 5,62

REPAIRS

Now done -

Bottom caulked and Sheathed with Yellow Metal on felt - about 350 treenails renewed in Bottom with Stringy Bark - and one lower deck half beam with Greenheart and the Hawse pipes refitted

Present Condition of the

Decks	good where seen	Treenails	350 renewed in bottom with Stringy Bark	Windlass and Capstan	good and efficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	good	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	where seen	Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelfs		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	caulked	~~Copper~~ Y.M. on felt When put on	now		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

She is now in our opinion fit for the conveyance of dry and perishable goods, to and from all parts of the world, and to remain as Classed

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : Rl

Certificate (if required) : :

A 1

H Cornish

B Waymouth

Committee's Minute 23rd October 1863

Character assigned 13 A 1

record

Charge £1-1-Rl

Rec'd 12.9.63

© 2021 Lloyd's Register Foundation

LON647-0427