26198

REPORT of SURVEY for REPAIRS.

No. 47 Survey held at London Dates 29th April & June 8th 1864.

on the Ship "Sir Robert Peppings" Master John Kay

Tonnage 606 628 Built at Moulmein When built 1844

By whom built Owners Allan

Port belonging to London Destined Voyage Madras

If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Docks

Last Survey, No. 25362 Port London Classed Rest. 62. Sp. A.I. 63

REPAIRS

Now done, - The Yellow Metal sheathing stripped off, the bottom caulked from keel to metal line, and resheathed with Yellow Metal on hair felt to 18 feet -

Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	and
Planksheers		Clamps and Shelfs		Anchors No. of	
Sheerstrakes		Ceiling		Cables	efficient
Topsides		Rudder		Hawsers and Warps	
Wales		Copper or Hair Felt When put on	now	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good when tested.

This vessel being now in an efficient condition, is in our opinion fit for the conveyance of dry and perishable goods to and from all parts of the world; and eligible to remain as classed.

The Amount of Fee £ : : is received by me,

Special 1 : 1 : - Paid 21/7/64 P. Waymouth

Certificate (if required) : : Rob. Thachan

Committee's Minute 14th June 1864

Character assigned Rest. 8 A 1

record

© 2019 Lloyd's Register Foundation

LR 628-0297