Change of Owners

*33592

# REPORT of SURVEY for REPAIRS.

Recd 20.2.74

in Book. No. _____ Survey held at London Date, first ~~Survey~~ Visit 15th February Last ~~Survey~~ Visit 11th February 1874

on the Ship "Godforth" Master _____

Tonnage 810 built at Shields. When built 1856

By whom built _____ Owners _____

Port belonging to Newcastle. Destined Voyage _____

If Surveyed Afloat or in Dry Dock Messrs Green's Dry Dock.

Last Survey, No. 32988 Port Chan. Classed 10 A 1 Lloyd's 66: 7yrs - (N.Y. Lon. 1869) "Repaired" 4/73.

~~REPAIRS, &c.~~

This Vessel has been sold to a Norwegian firm, - and they left a message for me at the Vessel - declining Survey.

J. D. Williamson

Present Condition of the

| | | |
|---|---|---|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained |
| Planksheers | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelfs | Anchors No. of |
| Topsides | Ceiling | Cables |
| Wales | Rudder | Hawsers and Warps |
| Plank (Bottom) and Counter | Copper When put on | Standing & Running Rigging |
| | Caulking of Bottom, Deck, & Waterways | |

Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations and Opinion,

The Amount of Entry Fee.....£ ⋮ ⋮ is received by me,

Special..... ⋮

Certificate (if required) ⋮ ⋮

Committee's Minute _____ 18____

Character assigned _____

[4,000—9/12/72.]

© 2021 Lloyd's Register Foundation

LON659-0152