36,220

# REPORT of SURVEY for REPAIRS, &c.

(Rec'd 24.5.77

No. in Reg. Book. **No.** 690 on the Schr Emulous — Survey held at London — Date, first Survey — Last Survey May 1st 1877 — Master

| | |
|---|---|
| **TONNAGE** under Tonnage Deck | 172 |
| Ditto of Spar Deck, or Awning Deck | |
| Ditto of Poop | |
| Ditto of Raised Qr. Dk. | |
| Ditto of Houses on Deck | |
| Ditto of Forecastle | |
| Gross Tonnage | |
| Crew Space, as per Rule | |
| Register Tonnage, cut on Beam | |
| Engine Room | |
| Reg. Tons as St'mer, cut on Bm. | |

Official Number

Built at Ipswich — When built (YEAR.) 1840 (MONTH.)

Owners Thomas Weston & Co — Port belonging to London

Residence

By whom built — Destined Voyage

If Surveyed Afloat or in Dry Dock Dry Dk

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

| | Years assigned. | Character in Register Book. |
|---|---|---|
| Classed | 12 | A 1 Red ~~Con 3~~ |
| | Rest | 5 8 C3 |

Last Survey, No. 35540 Port London

88 Lon 71. 5 yrs in Rest. 6.76 Expired

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

At present
I was asked to look at the Yellow Metal of this vessel which is in good condition.

The owner or Manager declines to have her Surveyed for Class at the present time as our Best
The Surveyors of another Registry have Surveyed her & there has been additional Outside bolts introduced with the 4 Strakes above the Metal being Yellow Metalled up to the 4th Strake below the Planksheer

Jenkinson Martindale

Present Condition of the

| | | |
|---|---|---|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained |
| Planksheers | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelfs | Anchors No. of |
| Topsides | Ceiling | Cables |
| Wales | Rudder | Hawsers and Warps |
| Plank (Bottom) and Counter | ~~Copper~~ Y Metal When put on 1874 | Standing & Running Rigging |
| | Caulking of Bottom, Deck, & Waterways | |

Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches

General Observations, Opinion as to Class, &c.

The Amount of Entry Fee ... ... ...£ : : received by me,
Special ... ...£ : : 187
Certificate (if required) ... ...£ : :
(Travelling Expenses, if any, £ )

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 18

Character assigned

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

[3,000—21/7/76.]

© 2021 Lloyd's Register Foundation

LON662-0149