12/5/82

ANNUAL SURVEYS.

41485

(Received at London Office, RECEIVED 13th MAY 82.)

No. ✓ Survey held at London Date, first Survey April 27th Last Survey May 9th 1882

No. in Reg. Book. 623 on the SS Shoreham Master G Irine

Tonnage { Net 293 Gross 451 Under Dk. 424 } Built at Pt Glasgow When built Year. 1872 Month. 8

By whom built Macfadzen Owners S Clarke & Co

Port belonging to London Destined Voyage Coal Trade

If Surveyed Afloat or in Dry Dock Poplar Victoria Dk (State Name of Dock.)

Last Survey, No. 40728 Port of Lond Classed Years assigned. 90 A1. 8.81 Character in Register Book. SS Lon M 2.81

Present Condition of the Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Treenails Rivets Good

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Ditto ditto at other places "

Keelsons "

Clamps and Shelfs "

Ceiling "

Rudder "

~~Copper or Y.M.~~ Coated When put on new

Caulking of Bottom, Deck, & Waterways Good

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Condition, how ascertained Sam Dk

Sails Good

Anchors, No. of 3 Bro. St & Nedys

Cables Part on St Good

Hawsers and Warps "

Standing and Running Rigging "

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "

(If a Steam Ship, state if a Report is also sent on the Machinery .....)

General Observations, Opinion as to Class, &c. Owing to damage one Strk broken plate at the Stem new and one small doubling plate riveted on another Stem plate. A few rivets renewed and Rudder put to right. Bottom to coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, 23rd May, 1882.

Character assigned 90 A1

Lenhouse Martineau

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) 5/- Paid 25/5 1882

(Insert Character precisely as in Register Book.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master

Tonnage { Net Gross Under Dk. } Built at When built Year. Month.

By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelfs

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

(If a Steam Ship, state if a Report is also sent on the Machinery .....)

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(Insert Character precisely as in Register Book.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

No. 1 for Annual Survey, where there are no repairs. 4000—6/12/80.)

© 2021 Lloyd's Register Foundation

LON668-0184