# ANNUAL SURVEYS.

42007

(Received at London Office, 2. 12. 82.)

**No.** _____ Survey held at London Date, first Survey 4th Novr Last Survey 27th Novr 1882 (No. of Visits _____)

No. in Reg. Book. 149 on the Iron Screw Schooner "Teviot." Master M. Duff.

Tonnage { Net 1349 Gross 2057 Under Dk. 1886 } Built at Sunderland When built Year. 1871 Month. 6th

By whom built J. Laing Owners J. Laing.

Port belonging to London Destined Voyage Bombay

If Surveyed Afloat or in Dry Dock In Dry Dock of Thames Iron Works. (State Name of Dock.)

Last Survey, No. 5795 Port of Lpt

Classed | Years assigned. | Character in Register Book. 100 A.1. S.S. Sld. No 2-80. 7.82

Present Condition of the Decks good; Waterways Do; Comings Do; Upper Deck Beams & Fastenings Do; Lower Deck Beams & Fastenings Do; Planksheers Do; Sheerstrakes Do; Topsides Do; Wales Do; ~~Plank~~ Plating (Bottom) and Counter Do

~~Treenails~~ Rivets — good; Breasthooks and Stemson Do; Transoms, ~~Pointers~~, and Crutches Do; ~~Timbers of~~ the Frame at the Openings Do; ~~Ditto~~ ditto at other places Do; Keelsons Do; ~~Clamps and Shelfs~~; Ceiling Do; Rudder Do; ~~Copper or Y.M.~~ ~~When put on~~; Caulking of Bottom, Deck, & Waterways good

Windlass and Capstan good; Pumps Do; Boats Do; Masts, Yards, &c. Do; Condition, how ascertained from the deck; Sails good; Anchors, No. of 3 B. 15. 2K.; Cables good; Hawsers and Warps Do; Standing and Running Rigging Do

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.

The bottom has been examined & coated.
This vessel appears to be in good & efficient condition & eligible to remain as classed.

Committee's Minute Tuesday, 12th December, 1882

Character assigned 100 A.1

J. A. Truscott.
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

---

**No.** _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____ (No. of Visits _____)

No. in Reg. Book. _____ on the _____ Master _____

Tonnage { Net _____ Gross _____ Under Dk. _____ } Built at _____ When built Year. _____ Month. _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____

Classed | Years assigned. | Character in Register Book.

Present Condition of the Decks; Waterways; Comings; Upper Deck Beams & Fastenings; Lower Deck Beams & Fastenings; Planksheers; Sheerstrakes; Topsides; Wales; Plank (Bottom) and Counter

Treenails; Breasthooks and Stemson; Transoms, Pointers, and Crutches; Timbers of the Frame at the Openings; Ditto ditto at other places; Keelsons; Clamps and Shelfs; Ceiling; Rudder; Copper or Y.M. _____ When put on _____; Caulking of Bottom, Deck, & Waterways

Windlass and Capstan; Pumps; Boats; Masts, Yards, &c.; Condition, how ascertained; Sails; Anchors, No. of; Cables; Hawsers and Warps; Standing and Running Rigging

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18 _____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

LON669-0340

© 2021 Lloyd's Register Foundation