Damage Repairs

42021

REPORT of SURVEY for REPAIRS, &c.

No. (Received at London Office, Tuesday, 10th December, 82)

No. in Reg. Book. 131 — Survey held at London — Date, first Survey Dec 4 — Last Survey 12 Dec 1882 — (No. of Visits 8)

on the SS Camilla — Master Haydon

Official Number

TONNAGE under Tonnage Deck	820
Ditto of Spar Deck, or Awning Deck	
Ditto of Poop	
Ditto of Raised Qr. Dk.	
Ditto of Houses on Deck	
Ditto of Forecastle	
Gross Tonnage	956
Crew Space, as per Rule	
Register Tonnage, cut on Beam	
Engine Room	
Reg. Tons as St'mer, cut on Bm.	722

Built at Newcastle — When built (Year) 1866 (Month)

Owners Lon Stm Ship Co — Port belonging to London

Residence

By whom built Palmer Bro — Destined Voyage Cardiff

If Surveyed Afloat or in Dry Dock Portsm Victoria Dock (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Years assigned. Character in Register Book.

Classed 100 A1 4.82

SS Lon W.S. 7.9.

Last Survey, No. 5645 **Port** Hull

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

At Present owing to Damage.

Portside abreast 4 Lower hold beams.

Renewed 2 Outside Plates, one bent Plates heated on Ships side and made fair, one frame shifted and butt strapped, 2 frames strengthened with additional angle Irons, one new outside butt strap double riveted, one new Lower hold Beam Stringer plate with angle Iron to ditto. one new Knee plate to Bracket-beam, or short beam.

a short length of Waterway on Starboardside of Deck new Pitch Pine. Deck Bridge repaired. Open rivets renewed in Bilge

Present Condition of the Decks	Gd	Treenails Rivets	Gd	Windlass and Capstan	Gd
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Coamings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	From Dk
Planksheers	"	Keelsons	"	Sails	Gd
Sheerstrakes	"	Clamps and Shelfs	"	Anchors No. of 3 Bro. & 1 Reserve	
Topsides	"	Ceiling	"	Cables Part on Dk	Gd
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	~~Copper (or Y.M.)~~ Part coated When put on	now	Standing & Running Rigging	"
		Caulking of Bottom, Deck, & Waterways	Gd		

Engine Room Skylights Gd — Coal Bunker, Openings, Lids, &c. Gd — Scuppers Gd — Cargo and Main Hatchways Gd — Hatches "

General Observations, Opinion as to Class, &c. Bottom Part coated.

She is now in an efficient state and eligible to remain as classed.

Damage Fee £

Amount of Entry Fee ... ...£ : : received by me, 188

Special ... ...£ : : 14/12/82

Certificate (if required) to be sent as per margin... £ : :

(Travelling Expenses, if any, £)

Committee's Minute Tuesday, 10th December, 188

Character assigned 100 A1

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.

© 2021 Lloyd's Register Foundation

LON669-0354

(Insert Character precisely as in Register Book.)