42625

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, July 4th 83

Survey held at London — Date, first Survey 16th May — Last Survey 26th June 1883
(No. of Visits)

on the Iron Ship "Serapis." — Master J. Gray.

NAGE under Tonnage Deck	933	Built at Greenock.	When built 1876 (YEAR.) 11th (MONTH.)
o of Spar Deck, or Awning Deck		Owners W. Lund.	Port belonging to London.
o of Poop		Residence	
tto of Raised Qr. Dk.		By whom built J. E. Scott.	Destined Voyage Adelaide
itto of Houses on Deck		If Surveyed Afloat or in Dry Dock (State Name of Dock) In the Ratcliff Dry Dock.	
Ditto of Forecastle			
Gross Tonnage	1027		
Crew Space, as per Rule			
egister Tonnage, cut on Beam	995		
ngine Room			
eg. Tons as St'mer, cut on Bm.			

gth of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Classed — Years assigned. — Character in Register Book. 100A.1

ast Survey, No. 4082 Port Lon — S.S. Lon. No 1-81. 9.81

PAIRS, OR EXAMINATION AS PER RULE
Cause of Repairs to be clearly stated.

Society's Load-Line (if assigned) as painted on Ship

Society's Freeboard (~~if~~ or now assigned) as painted on Ship {ft. ins 4 - 0 salt, 3 - 8 fresh}

(Insert Character precisely as in Register Book.)

Part special survey No 2.

This vessel has been placed in dry dock and the bottom examined & coated. The limber boards and ceiling in excess of three strakes fore and aft on each side removed; the cement examined and a large part renewed. Part of the close ceiling in hold renewed. The hold from the top of close ceiling to lower deck beams cleaned & coated.
On account of damage, part of poop deck renewed of 3" yellow pine; several main bulwark stanchions renewed and others repaired.

ent Condition of the		~~Treenails~~ Rivets —	good	Windlass and Capstan	good
s	good	Breasthooks and Stemson	Do	Pumps	Do
erwags	Do	Transoms, ~~Pointers~~, and Crutches	Do	Boats	Do
ings	Do	~~Timbers of~~ the Frames at the openings	Do	Masts, Yards, &c.	Do
r Deck Beams & Fastenings	Do	~~Ditto~~ Ditto at other places	Do	Condition, how ascertained	from the deck
r Deck Beams & Fastenings	Do	Keelsons	Do	Sails	good
ksheers	Do	~~Clamps and Shelfs~~		Anchors No. of	3 B. 1 S. 2 K.
strakes	Do	Ceiling	Do	Cables	good
des	Do	Rudder	Do	Hawsers and Warps	Do
s	Do	~~Copper (or Y.M.)~~ ~~(State if on Felt.)~~ ~~When put on~~		Standing & Running Rigging	Do
ing (Bottom) and Counter	Do	Cement (if Iron Ship)	good		
		Caulking of Bottom, Deck, & Waterways	good		

~~ne Room Skylights~~ ~~Coal Bunker, Openings, Lids, &c.~~ Scuppers good Cargo and Main Hatchways good Hatches good

ral Observations, Opinion as to Class, &c.

This vessel is in good and efficient condition and eligible in my opinion remain as classed.

21.6
4.0

Amount of Entry Fee ... ...£ — : — : — received by me, 3/8 1883 F.F.E.
Special ... ...£ 2 : 2 : — } See Freeboard Rpt
Certificate (if required) to be sent as per margin... } £ : 5 :

J. H. Truscott.
Surveyor to Lloyd's Register of British and Foreign Shipping.

lling Expenses, if any, £)

nmittee's Minute FRIDAY 6 JULY 1883 18

racter assigned 100A

TBW (Note part S.S. No 2-83)

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.

© 2021 Lloyd's Register Foundation

LON670-0436