ANNUAL SURVEYS.

43167

(Received at London Office, FRIDAY 9 NOV 1883)

No. _____ Survey held at London Date, first Survey 3rd Novr Last Survey 1st Novr 1883 (No. of Visits _____)

No. in Reg. Book 233. on the Iron Scw. Bq. "Eldorado." Master L. A. J. Bergemann.

Tonnage { Net 2157 / Gross 3332 / Under Dk. 2128 } Built at Hull When built 1873 (Year.) 3rd (Month.)

By whom built Earles' Co. Owners A. Gray & E. S. Dawes.

Port belonging to Glasgow. Destined Voyage Calcutta.

If Surveyed Afloat or in Dry Dock (State Name of Dock.) Royal Albert Dry Dock. Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. 42637 Port of Lon. Classed — Years assigned: _____ Character in Register Book: 100 A·1. S.S. Lon. No 2-81. 5,83

Present Condition of the Decks: good
Waterways: Do.
Comings: Do.
Upper Deck Beams & Fastenings: Do.
Lower Deck Beams & Fastenings: Do.
Planksheers: Do.
Sheerstrakes: Do.
Topsides: Do.
Wales: Do.
Plank (Bottom) and Counter: Do.

~~Treenails~~ Rivets — good
Breasthooks and Stemson: Do.
Transoms, ~~Pointers~~, and Crutches: Do.
~~Timbers of~~ the Frames at the Openings: Do.
~~Ditto ditto at other places~~
Keelsons: Do.
~~Clamps and Shelfs~~
Ceiling: Do.
Rudder: Do.
~~Copper or Y.M.~~ ~~When put on~~
Caulking of Bottom, Deck, & Waterways: good

Windlass and ~~Capstan~~ steam winches: good
Pumps: Do.
Boats: Do.
Masts, Yards, &c.: Do.
Condition, how ascertained: from the deck
Sails: good
Anchors, No. of: 3 B. 1 S. 2 K.
Cables: complete
Hawsers and Warps: good
Standing and Running Rigging: Do.

Engine Room Skylights: good Coal Bunkers, Openings, Lids, &c.: good Scuppers: good Cargo and Main Hatchways: good Hatches: good.

General Observations, Opinion as to Class, &c. The bottom has been examined & coated. This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TBM TUESDAY 20 NOV 1883

Character assigned TBM 100 A 1

BS 11, 83 (23/11/83)

J. H. Truscott.
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) 5/- Paid 7/12 1883 F.F.E.

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18__ (No. of Visits _____)

No. in Reg. Book. on the _____ Master _____ (Year.) (Month.)

Tonnage { Net / Gross / Under Dk. } Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock (State Name of Dock.) _____ Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. _____ Port of _____ Classed — Years assigned: _____ Character in Register Book: _____

Present Condition of the Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelfs
Ceiling
Rudder
Copper or Y.M. _____ When put on _____
Caulking of Bottom, Deck, & Waterways

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c.

Committee's Minute _____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18__

(If a Steam Ship, state if a Report is also sent on the Machinery YES OR NO)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

Survey, when there are no repairs. 4000—18/5/83.)

© 2021 Lloyd's Register Foundation

LON671-0360