3/11/83

ANNUAL SURVEYS.

43178

(Received at London Office, THURSDAY 15 NOV 1883)

No. _____ Survey held at London Date, first Survey 7 Nov Last Survey 9 Nov 1883

No. in Reg. Book. 598 on the SS Lombard Master Hutton

Tonnage { Net 1132 Gross 1750 Under Dk. 1645 } Built at Newcastle When built Year. 1877 Month. 3

By whom built Tyne S B Co Owners T. H. Davison

Port belonging to London Destined Voyage Not known

If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock (State Name of Dock.)

Last Survey, No. 5727 Port of Dept

Classed | Years assigned. 100 | Character in Register Book. A1 11.82 SS AL Nov 1.82

Present Condition of the Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Treenails Rivets Good

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Ditto ditto at other places "

Keelsons "

Clamps and Shelfs "

Ceiling "

Rudder Bushes "

~~Copper or Y.M.~~ Coated When put on new

Caulking of Bottom, Deck, & Waterways Good

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Condition, how ascertained Inspection

Sails Good

Anchors, No. of 3 Bes, 1 & 1 Kedge

Cables Parton 1st Good

Hawsers and Warps "

Standing and Running Rigging "

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "

(If a Steam Ship, state if a Report is also sent on the Machinery .....)

General Observations, Opinion as to Class, &c. Bottom re coated & Rudder Bushed

She is now in an efficient state and eligible to remain as classed.

Lenhouse Martindale

Committee's Minute _____ FRIDAY 23 NOV 1883 18 _____

Character assigned 100 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____

No. in Reg. Book. _____ on the _____ Master _____

Tonnage { Net _____ Gross _____ Under Dk. _____ } Built at _____ When built Year. _____ Month. _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____

Classed | Years assigned. | Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelfs

Ceiling

Rudder

Copper or Y.M. _____ When put on _____

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

(If a Steam Ship, state if a Report is also sent on the Machinery .....)

General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18 _____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

(Form No. 4 for Annual Survey, when there are no Committee's Minute.) 4000—6/12/80.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

© 2021 Lloyd's Register Foundation