ANNUAL SURVEYS.

43473

(Received at London Office THURSDAY 14 FEB 1884)

No. _____ Survey held at London Date, first Survey January 7th Last Survey January 16th 1884

No. in Reg. Book. 513 on the Iron Ship "Golden Horn" (No. of Visits ____) Master Parr

Tonnage: Net 1842 Gross 1915 Under Dk. 1753 Built at Greenock When built Year. 1883 Month. 1

By whom built Russell & Co Owners J. R. De Wolff

Port belonging to Liverpool Destined Voyage Liverpool

If Surveyed Afloat or in Dry Dock (State Name of Dock.) Union Dock & afloat Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. 28624 Port of Liverpool Classed — Years assigned. — Character in Register Book. 100 A 1

MOULDED DEPTH of Ship, if not yet recorded in Register Book 2,83

Present Condition of the Decks: good; Waterways: "; Comings: "; Upper Deck Beams & Fastenings: "; Lower Deck Beams & Fastenings: "; Planksheers: "; Sheerstrakes: "; Topsides: "; Wales: "; ~~Plank~~ (Bottom) and Counter: "

~~Freemils~~ Rivets where seen good; Breasthooks and Stemson: " "; Transoms, Pointers, and Crutches: " "; ~~Timbers of the~~ Frame at the Openings: " "; Ditto ditto at other places: not seen; Keelsons: where seen good; Clamps and Shelfs: " "; Ceiling: " "; Rudder: " "; ~~Copper or Y.M.~~ Cemented When put on 1883; Caulking of Bottom, Deck, & Waterways: Good

Windlass and Capstan: Good; Pumps: "; Boats: "; Masts, Yards, &c.: "; Condition, how ascertained: by observation; Sails: Sufficient; Anchors, No. of: 3 B, 1 S & 2 K; Cables: part seen good; Hawsers and Warps: sufficient; Standing and Running Rigging: — " —

Engine Room Skylights: — Coal Bunkers, Openings, Lids, &c.: — Scuppers: Good Cargo and Main Hatchways: Good Hatches: Good

General Observations, Opinion as to Class, &c. This vessel has now been placed in Dry Dock the bottom examined and recoated with paint, a new Iron Cap (instead of Cast Steel damaged) fitted to the Foremast & Iron Work to Yards repaired, and steering gear repaired, - is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 15 FEB 1884 Character assigned TBM 100 A 1

Jno Wm Miles. Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) ____ Paid ____ 18__

No. _____ Survey held at London Date, first Survey January 30th Last Survey February 13th 1884

No. in Reg. Book. 682 on the Iron Ship "Sir Walter Raleigh" (No. of Visits ____) Master Purvis

Tonnage: Net 1492 Gross 1579 Under Dk. 1383 Built at Glasgow When built Year. 1876 Month. 2

By whom built J. & G. Thompson Owners D. Rose & Co.

Port belonging to Aberdeen Destined Voyage Sydney

If Surveyed Afloat or in Dry Dock (State Name of Dock.) South West India Dock Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. 41381 Port of London Classed — Years assigned. — Character in Register Book. 100 A 1

MOULDED DEPTH of Ship, if not yet recorded in Register Book S.S. Lon No 1-80 4.82

Present Condition of the Decks: good; Waterways: "; Comings: "; Upper Deck Beams & Fastenings: "; Lower Deck Beams & Fastenings: "; Planksheers: "; Sheerstrakes: "; Topsides: "; Wales: "; ~~Plank~~ (Bottom) and Counter: where seen good

~~Freemils~~ Rivets where seen good; Breasthooks and Stemson: " "; Transoms, Pointers, and Crutches: " "; ~~Timbers of the~~ Frame at the Openings: " "; Ditto ditto at other places: not seen; Keelsons: good; Clamps and Shelfs: "; Ceiling: "; Rudder: "; Copper or Y.M. Cemented When put on 1876; Caulking of Bottom, Deck, & Waterways: Good

Windlass and Capstan: Good; Pumps: "; Boats: "; Masts, Yards, &c.: "; Condition, how ascertained: by observation; Sails: Sufficient; Anchors, No. of: 3 B, 1 S & 2 K; Cables: part seen good; Hawsers and Warps: sufficient; Standing and Running Rigging: — " —

Engine Room Skylights: — Coal Bunkers, Openings, Lids, &c.: — Scuppers: Good Cargo and Main Hatchways: Good Hatches: Good

General Observations, Opinion as to Class, &c.

This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

The owners intend to have her docked and submitted to Survey Number 2 on her return from the present voyage, see their letter to Secretary dated 26/1/84

Committee's Minute FRIDAY 15 FEB 1884 Character assigned TBM 100 A 1

Jno Wm Miles. Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) ____ Paid ____ 18__

(If a Steam Survey, state if a Report is also sent on the Machinery.) (The Surveyors are requested not to write on or below the space for Committee's Min.) (Insert Character precisely as in Register Book.)
(The Surveyors are requested not to write on or below the space for Committee's Minute.) (Insert Character precisely as in Register Book.)
LON672-0117
Lloyd's Register Foundation ©2024