44080

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,)

No. ____ No. in Reg. Book. 295 Survey held at London Date, first Survey 30 July Last Survey 31 188 4

on the Machinery of the Henry Morton (Number of Visits 2)

Tonnage, Gross 993 Built at Newcastle When built (Year) 1850 (Month)

Ditto, Net 634 Owners J. Fenwick & Sn. Port belonging to London

Diameter of Cylinder 26 57 Engines made by Vic Dk Eng Wks. When made (Year) 1874

Length of Stroke 30 Boilers made by When made (Year) 1874

Pressure of Steam 75 If Surveyed Afloat or in Dry Dock (State name of Dock.) Pontoons Classed (Character in Register Book.) A 1.

Registered Horse Power 99 11 83

Last Survey No. Port MS. 9.82. BS. 3.83.

Particulars of Repairs and Examination Boiler Survey

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined seacocks and connections and found them good.

Examined condenser and found it good. Several tubes had been renewed.

Examined safety valves (loaded levers) and found them in a good working condition

Examined Superheater and found it in a good condition.

Examined ~~2 boilers~~ 2 main boilers & found them in a good condition. A few patches and rivets in the furnaces had been repaired or renewed.

It is submitted that this vessel is eligible to have the notification BS. 7.84 recorded, the boilers being subject to scaling as per Rule

JM 11/8/84

General Observations, Opinion, and Recommendation :— As far as seen the machinery of this vessel appears to be in a safe working condition and eligible in my opinion to have the notification B.S. 7.84 recorded in the Register Book

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Survey Fee (per Section 28) £ 2 2 -

14/8/84

Special Damage Fee (per Section 28) £ : :

*Certificate (if required) £ : :

Travelling Expenses (if chargeable) £ : :

received by me, 16th August 1884 A.J.S.

C W Stromeyer

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRIDAY 15 AUGUST 1884

Committee's Minute

Assigned B.S. 7.84

(The Surveyors are requested not to write on or below the space for Committee's Minute).

(State if a report is also sent on the Hull of the Ship.)

Insert Character of Ship and Machinery precisely as in the Register Book.

© 2021 Lloyd's Register Foundation

LON673-0132