44606

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office, FRIDAY 30 JAN 1885)

No. 1

No. in Reg. Book. 829 Survey held at London Date, first Survey 29th Nov 84 Last Survey 20 Jany 1885

on the Machinery of the S. S. Methven Castle (Number of Visits 2)

Tonnage, Gross 2681 Built at Glasgow When built Year 1883 Month 9

Ditto, Net 1740 Owners D. Currie & Co Port belonging to London

Diameter of Cylinder 36 68 Engines made by Barclay Curle & Co When made Year 1883

Length of Stroke 48 Boilers made by When made Year 1883

Pressure of Steam 80 If Surveyed Afloat or in Dry Dock E. T. Dock (State name of Dock.) Classed Character in Register Book. 100 A1 11 83

Registered Horse Power 270 + L M C 11 83.

Last Survey No. 6314 Port Glas

Insert Character of Ship and Machinery precisely as in the Register Book.

Particulars of Repairs and Examination Defective tunnel shaft

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined defective tunnel shaft. (diagonal zig zag flaw) and recommended new one to be fitted.
The new shaft is roughly turned except at bearing and appears to be sound.

It is submitted that this vessel is eligible to remain as classed
JM 29/1/85

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to remain as classed

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec. 27)	£ : :	received by me, 188
Survey Fee (per Section 28)	£ — : — : —	
Special Damage Fee (per Section 28)	£ — : — : —	
Certificate (if required)	£ — : — : —	
Travelling Expenses (if chargeable)	£ — : — : —	

C. W. Stromeyer
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUESDAY 3 FEB 1885

Assigned JAM W S Reed

© 2021 Lloyd's Register Foundation

LON674-0170