REPORT of SURVEY for REPAIRS, &c.

47288

No. 47288 Port of London

Received in London Office, WEDNES. 8 JUNE 1887

No. in Reg. Book. 362 Survey held at Limehouse Date, First Survey 12th May Last Survey 15 May 1887 (No. of Visits)

on the Iron Bk "Alcestis" Master A Harris

TONNAGE:— NET 398 GROSS 423 UNDER DK 397

Built at Sunderland By whom Duff & Mounsey When 1868 (YEAR.) 5 (MONTH.)

Owners E. B. Stone Port belonging to Auckland

Owners' Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Name of Dock Limehouse Destined Voyage Bluff Harbour New Zealand

Length of Poop ft.: of Forecastle ft.: of Raised Qr. Deck ft.: Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Classed — Years assigned, if a Wood Ship. — Character in Register Book. *A/A 1 6.86

Last Survey, No 46284 Port London SS Lloyds 3.81 SS Lloyds 1.85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship: in Summer ft. ins. in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual

Bottom recoated, Rudder pintles rebushed. Some ceiling renewed

PRESENT CONDITION OF THE

Decks	Good	~~Blank~~ (Bottom) & Counter	Good	Ceiling	Good	Boats	3 Ro Good
Waterways	—	~~Treenails or~~ Rivets	—	Rudder	—	Masts, Yards, &c.	—
Comings	—	Breasthooks ~~& Stemson~~	—	Windlass & Capstan	—	Condition, how ascertained	Rough Dk
Up'r Dk. Beams & Fastenings	—	Transoms, Pointers, & Crutches	—	Pumps	2 Ro	Sails	Good
Low'r Dk. Beams & Fastenings	—	~~Timbers of~~ Frame at the openings	—	Cement (if Iron Ship)	—	Anchors No. of	3 B. 1 S & 2 K
Planksheers	—	~~Ditto~~ ditto at other places	—	Caulk'ng of Bot'm, D'k, & Watrwys		Cables	Part seen Good
Sheerstrakes	—	Keelsons	—	Copper, or Y.M. (State if on Felt.) When put on		Hawsers & Warps	—
Topsides	—	Clamps & Shelfs				Standing & Running Rigging	—
Wales	—						

Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo & Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, Recommendation, &c.:

She appears in good condition and in my opinion eligible to continue as Classed

Entry Fee (if chargeable) *per Scale I., Sec. 27...*	£	:	:
Office Fee (if chargeable) *per Scale II., Sec. 27...*	£	:	:
Survey Fee (*per Section 28*)	£	:	:
Special on Damage, Fee (if any) (*per Sec. 28*)	£	:	:
*Certificate (if required) *to be sent as per margin*	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees received by me, 188

Wm. C. Davey
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 10 JUNE 1887

Character assigned *A/A 1

(If a Steam Ship, state particularly whether or not a Report is also sent on the Machinery)

* Certificate to be sent to

(Insert Character precisely as in Register Book.)

The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Form No. 2 for Repairs—5000—21/3/87.—Transfer Ink.—T. & S.)

LON680-0223

© 2021 Lloyd's Register Foundation

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.