48842

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, WEDNES. 17 OCT 1888

No. ..... Date of Writing Report ..... 188 ..... Port of London

No. in Reg. Book. 70 Survey held at London Date, First Survey 29th Aug. Last Survey 16th Oct. 1888 (No. of Visits .....)

on the Ship "Taranaki". Master

TONNAGE:— NET 1130 GROSS 1199 UNDER DK. 1042

Built at Port Glasgow By whom R. Duncan & Co When Year 1877 Month

Owners John Leslie Port belonging to Glasgow

Owners' Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Name of Dock Greens Destined Voyage ~~Wind~~ Otago

Length of Poop ..... ft.: of Forecastle ..... ft.: of Raised Qr. Deck ..... ft.: Moulded Depth ..... ft. ..... ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 47636 Port Lon

	Years assigned, if a Wood Ship.	Character in Register Book.
Classed		100 A1
	S.S. No. 2. 85.	9.87

Society's Freeboard (if assigned) as painted on Ship: in Summer ..... ft. ..... ins.; in Winter ..... ft. ..... ins.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

The bottom outside is in good order, it has been cleaned and coated.
A new 9½" Manilla hawser has been supplied.

PRESENT CONDITION OF THE

Decks	Good	Plank (Bottom) & Counter	Good	Ceiling	Good	Boats	Good
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained	from deck
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of	2/3. 1 S. 2/K
Planksheers		Ditto ditto at other places	"	Caulk'ng of Bot'm, D'k, & Watrwys	"	Cables	Port - seen good
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.) When put on		Hawsers & Warps	
Topsides	"	Clamps & Shelfs				Standing & Running Rigging	Good
Wales							

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo & Main Hatchways Good Hatches "

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28)	£	:	:
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees applied for, ... 188 .....
Received by me, ... 188 .....

Allison B. Wilson.
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 19 OCT 1888
Character assigned 100A1

State if a Report is also sent on the machinery of the Ship or if not whether, and when, one will be sent.

* Certificate to be sent to

The Surveyors are requested not to write on or below the space for Committee's Minute.

[Form No. 2 for Repairs—1,000—12/1/88.—T. and E. Ink.—T. & S.]

© 2019 Lloyd's Register Foundation

LON684-0139

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.