49018

REPORT of SURVEY for REPAIRS, &c.

No. ..... Date of Writing Report Dec 7 2nd 3 1888 Port of London Received in London Office, SAT 22 DEC 1888

No. in Reg. Book. Survey held at London Date, First Survey — (No. of Visits) Last Survey Dec 21 1888

727 on the British Queen Steel Sr Master Will

TONNAGE:— [redacted] 7 Built at Belfast By whom Harland & Wolff When 1880 - 11 (YEAR. MONTH.)

GROSS [redacted] 958 Owners British Shipowners Coy Ltd Port belonging to Liverpool

UNDER DK. 3294 Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock afloat Name of Dock Victoria Wk Destined Voyage New York

Length of Poop ft.: of Forecastle ft.: of Raised Qr. Deck ft.: Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Classed — Years assigned, if a Wood Ship. — Character in Register Book. 100 A.1. 11-88

Last Survey, No. 48950 Port London

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship: in Summer ft. ins.; in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S Survey No. 2

The Port engine Room bunker has now been examined to complete Survey

T C M 6/1/89

PRESENT CONDITION OF THE Mast where seen

Decks	Good	Plank (Bottom) & Counter	Good	Ceiling	Good	Boats	Good
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	from Dk
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"	Cement (if Iron Ship)	"	Anchors No. of	3B, 1S, 2K
Planksheers	"	Ditto ditto at other places	"	Caulk'ng of Bot'm, D'k, & Watrwys	"	Cables	Good
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	—	Hawsers & Warps	"
Topsides	"	Clamps & Shelfs	"	When put on	—	Standing & Running Rigging	"
Wales	"						

Engine Room Skylights ..... Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo & Main Hatchways Good Hatches "

General Observations, Opinion as to Class, Recommendation, &c.:

This Vessel now appears to be in a sound & efficient condition eligible in my opinion to remain as classed & to have the Special Survey No 2 recorded

	£	:	
Entry Fee (if chargeable) per Scale I., Sec. 27			Dr 4/3/89
Office Fee (if chargeable) per Scale II., Sec. 27			
Survey Fee (per Section 28)		1	9
Special on Damage, Fee (if any) (per Sec. 28)			
*Certificate (if required) to be sent as per margin			
Travelling Expenses (if chargeable)			
Second Surveyor's Fee (if any)			

Fees applied for, 24. 12 1888

Received by me, 6/3 1889

Edward McGuinness

Surveyor to Lloyd's Register of British & Foreign Shipping.

THURS 27 DEC 1888 — TUES 1 JAN 1889

Committee's Minute

Character assigned 100A1

SS No: 2-88

LON684-0389

* Certificate to be sent to .....

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent.

Insert Character precisely as in Register Book.

[Form No. 2 for Repairs—10000—12/9/88—Transfer Ink.—T & S.]

The Surveyors are requested not to write on or below the space for Committee's Minute.

© 2019 Lloyd's Register Foundation

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.