57291

REPORT of SURVEY for REPAIRS, &c.

Received in London Office THURS 13 NOV 1890

No. 1 Date of Writing Report 13/11/90 18 Port of London

No. in Reg. Book. 1478 Survey held at London Date, First Survey Oct 6 3/89 Last Survey Nov 5 3 1890
(No. of Visits)

on the Star of Bengal Iron S. Master Mr Lyle

TONNAGE:— NET 1797 GROSS 1877 UNDER DK. 1684

Built at Belfast By whom Harland & Wolff When 1874 YEAR. MONTH.

Owners J. P. Corry & Coy Port belonging to Belfast

Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dk Name of Dock Green's Destined Voyage Melbourne

Length of Poop ft.: of Forecastle ft.: of Raised Qr. Deck ft.: Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship. Character in Register Book.

Classed 100 A 1

Last Survey, No 80037 Port London — 28 Lon No 3 - 3/87 do 11-85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship: in Summer 5 ft. 3 ins. in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This Vessel was placed in dry dock the bottom examined cleaned and coated the rudder lifted and pintles bushed. New Fore top gallant mast, new Upper Fore top sail yard, new Upper Fore top gallant yard Supplied

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent

* Certificate to be sent to

Insert Character precisely as in Register Book.

PRESENT CONDITION OF THE

Decks	Good	Plank (Bottom) & Counter	Good	Ceiling	Good	Boats	Good
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	from DS
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"	Cement (if Iron Ship)	"	Anchors No. of	3 3, 1 S, 2 S
Planksheers	"	Ditto ditto at other places	"	Caulk'ng of Bot'm, D'k, & Watrwys	"	Cables	Good
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	—	Hawsers & Warps	"
Topsides	"	Clamps & Shelfs	"	When put on	—	Standing & Running Rigging	"
Wales	"						

Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo & Main Hatchways Good Hatches "

General Observations, Opinion as to Class, Recommendation, &c.:

This Vessel now appears to be in a Sound & efficient condition eligible in my opinion to remain as classed. & to have a record of last date of Survey 11/90

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28)	£	:	:
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any).....	£	:	:

Fees applied for, 18

Received by me, 18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRI 14 NOV 1890

Character assigned 100 A 1

[Form No. 2 for Repairs—10000—21/8/90.—Transfer Ink.—T & S.]

The Surveyors are requested not to write on or below the space for Committee's Minute.

© 2019 Lloyd's Register Foundation

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.