No. 56030

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office TUES. 4 DEC 1894)

Date of writing Report ____ 18 ____ When handed in at Local Office ____ 18 ____ Port of London

No. in Reg. Book. 2218 Survey held at London Date, First Survey Nov 22 Last Survey Nov 24 1894 (No. of Visits 2)

on the Machinery of the ~~Wood, Iron or~~ Steel S. S. "Wilcannia" Master ____

Tonnage	Gross 2718	Vessel built at Nwc.	By whom Wigham Richdsn. & Co	When (YEAR) 1883	(MONTH) 7
	Net 1750	Engines made at do	When 1888	Boilers, when made (Main) 1888	(Donkey)
Registered Horse Power	450	Owners W. Lund	Port	Voyage	
No. of Main Boilers	3	If Surveyed Afloat or in Dry Dock (State name of Dock.) London			
No. of Donkey Boilers	1				
Steam Pressure— in Main Boilers	150 lbs				
in Donkey Boilers					

Last Survey No. 55492 Port Lon

Particulars of Examination and Repairs (if any) Annl. B.S.

(Periodical Surveys, when held, must be reported in detail and periodically in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Particulars of Classification *(which must be inserted precisely as in Register Book & Supplements).*

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠100 A1		✠LMC 7.92
5.94		
S.S Lon. No 1-92		

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes.

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? yes.

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

The vessel is now laid up. Owners will advise when ready to complete survey.

To complete the survey the Donkey blr. & its Safety vals. have to be exams. & all the S. V. set under steam

General Observations, Opinion, and Recommendation:— The Main boilers being now in

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4.94, B.&M.S. 4.94 or ✠L.M.C. 4.94, 140 lb., F.D., &c.)

good & safe workg. condtn. renders the vessel eligible in my opinion to have the record B. S. 11. 94 on the satis. complen. of survey

Office or Registration Fee (per Sec. 37)	£ : :	Fees applied for 5.12.1894	AKD 10.
Survey Fee (per Section 28)	£ 2 : 10		
Special Damage Fee (per Section 28)	£ : :	Received by me, 10.12.94	
Travelling Expenses (if chargeable)	£ : :		

*State if Certificate is required

Geo. J. Wilkinson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

(The Surveyors are requested not to write on or below this line.)

Committee's Minute FRIDAY 7 DEC 1894 FRIDAY 25 JAN 1895

Assigned Defd for complen of B.S.

pc. B.S.

Insert Character of Ship and Machinery precisely as in the Register Book.

© 2019 Lloyd's Register Foundation
LON704-0013