Rpt. 8.

(Received at London Office WED. 20 JUL 1898)

No. 60102

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19th July 1898. When handed in at Local Office ..... 18 .... Port of London

No. in Reg. Book. 529 — Survey held at London — Date, First Survey 12th July, Last Survey 15th July 1898 (No. of Visits 3) — on the ~~Wood, Iron or~~ Steel SS "Greenbrier" — Master

TONNAGE:— GROSS 2875 — UNDER DK. 2703 — NET 1819

Built at W Hartlepool — By whom Furness Withy — When 1893 (Year) 12 (Month)

Owners Chesapeake & Ohio SS Co — Port belonging to W Hartlepool

Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed ~~Afloat or~~ in Dry Dock? — Name of Dock Albert Dk — Destined Voyage

WB=CellDBorDBa ..... feet; uE&B ..... feet; I ..... feet; total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 100 A1 Spar Dk 11.97		✠ LMC 8.97

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

Last Report, No. 59815 Port Lon

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Part SS No. 1

See Lon Report No. 59815

This survey has now been further advanced by the examination of the ballast tank under No. 3 hold

To complete the survey the tank under No. 2 hold has to be examined. The tanks under Nos 2 & 3 holds have to be tested, & No 2 hold & the machinery space to be examined. This it is intended to do on the vessels return.

The bottom has been examined in dry dock and some rivets renewed in the heel.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks: good
Caulking of Decks: "
Waterways: "
Coamings: "
Beams & Fastenings: ✓
Outside Plating: "
Caulking of ditto: "
Rivets: "
Breasthooks & Crutches: ✓
Transoms: ✓
Frames: ✓
Reverse Frames: ✓
Floors: "
Keelsons: "

Stringers: ✓
Inner Bottom Plating: good
State if Tanks now tested: no
Bulkheads: good
Ceiling: "
Cement ~~or Asphalt~~ (State which.): "
Rudder: "
Windlass: "
Have Pumps now been examined and found efficient? ✓
Have Sluice Valves now been examined and found efficient? ✓
Have Watertight Doors now been examined and found efficient? ✓
Dblng. Plates under Sounding Pipes: good

Engine Room Skylights: good
Coal Bunkers, Open'gs, Lids, &c.: "
Scuppers: "
Cargo Hatchways: "
Hatches: "
Planking of Wood Vessels: "
Treenails ditto: "
Breasthooks & Stemson ditto: "
Transoms, Pointers, & Crutches ditto: "
Timbers of Frame at openings ditto: "
Ditto ditto at other places ditto: "
Stringers, Clamps & Shelfs ditto: "
Salting (State if examined.) ditto: "
Copper, or Y.M. (State if on Felt.) ditto: "
When put on, Month ✓ Year

Boats: good
Masts, Yards, &c.: "
Condition, how ascertained: "
(State if wedges removed: no)
Sails: ✓
Equipment letter: V
Anchors, No. of: 5
Cables (State if now ranged): no
" length (on board) ✓ size
" Rule length (per Table 22) ✓ size
Hawsers & Warps: good
Standing & Running Rigging: "

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of *ss No.* 1–98 and ptND98, &c.."

This vessel now appears to be in good & efficient condition and is eligible in my opinion to remain as classed without record of survey.

Office Fee (if chargeable) per Scale II., Sec. 27 ..... £ : :
Survey Fee (per Section 28) ..... £ : :
Special Damage or Repair Fee (if any) (per Sec. 28.) ..... £ : :
Travelling Expenses (if chargeable) ..... £ : :
Second Surveyor's Fee (if any) ..... £ : :

Fees applied for, ... 18
Received by me, ... 18

Note

A Campbell-Johns
Surveyor to Lloyd's Register of British & Foreign Shipping.

FRI. 22 JUL 1898

Committee's Minute

Character assigned Deferred for compln. of No. 1

FRI. 7 OCT 1898

pt. no. 1

Has a Survey also been held on the Machinery of the Ship? If so, to the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

3145—500.—293/98.—Transfer Ink.

© 2019 Lloyd's Register Foundation
LON716-0114