Rpt. 8.

(Received at London Office SAT. 10 SEP 1898

No. 60247.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 9th Sep 1898. When handed in at Local Office ..... 18 ..... Port of London

No. in Reg. Book. 181

Survey held at London Date, First Survey 3d Sep Last Survey 8th Sep 1898 (No. of Visits 4)

on the ~~Wood, Iron or~~ Steel SS "Victoria" Master

TONNAGE:— GROSS 6849 UNDER DK. 6004 NET 4384

Built at W Hartlepool By whom Furness Withy When 1898 (YEAR.) 1 (MONTH.)

Owners Atlantic Transport Co Ltd Port belonging to W Hartlepool

Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed ~~Afloat or~~ in Dry Dock? Name of Dock Albert Dk Destined Voyage

WB=CellDBorDBa ..... feet; uE&B ..... feet; I ..... feet;
total capacity ..... tons; FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59693 Port Lon

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 100A1		✠ LMC 1.98
3.98		

Society's Freeboard (if assigned) as painted on Ship and now verified 7 ft. 8 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel has been examined in dry dock, the bottom cleaned & coated and some half-dozen rivets in rudder renewed.

Nos. 2, 4 & 5 lower 'tween decks have been insulated (at New York) In Nos. 4 & 5 the iron centre line shifting-board bulkhead has been removed, and in its place pillars and a double angle stringer fitted as required by the rules. No. 6 Bulkhead has been pierced with a doorway in the lower 'tween decks; it is no longer a W.T. partition & the record of Bulkheads in the Reg. book should be amended from 8 B.H. to 7 B.H..

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks: good
Caulking of Decks: "
Waterways: "
Coamings: "
Beams & Fastenings: ✓
Outside Plating: "
Caulking of ditto: "
Rivets: "
Breasthooks & Crutches: ✓
Transoms: ✓
Frames: ✓
Reverse Frames: ✓
Floors: ✓
Keelsons: ✓

Stringers: ✓
Inner Bottom Plating: ✓
State if Tanks now tested: ✓
Bulkheads: ✓
Ceiling: ✓
Cement or Asphalt (State which.): ✓
Rudder: good
Windlass: "
Have Pumps now been examined and found efficient?: ✓
Have Sluice Valves now been examined and found efficient?: ✓
Have Watertight Doors now been examined and found efficient?: ✓
Dblng. Plates under Sounding Pipes: ✓

Engine Room Skylights: good
Coal Bunkers, Open'gs, Lids, &c.: "
Scuppers: "
Cargo Hatchways: "
Hatches: "
Planking of Wood Vessels: ✓
Treenails ditto: ✓
Breasthooks & Stemson ditto: ✓
Transoms, Pointers, & Crutches ditto: ✓
Timbers of Frame at openings ditto: ✓
Ditto ditto at other places ditto: ✓
Stringers, Clamps & Shelfs ditto: ✓
Salting (State if examined.) ditto: ✓
Copper, or Y.M. (State if on Felt.) ditto: ✓
When put on, Month ..... Year .....

Boats: good
Masts, Yards, &c.: "
Condition, how ascertained: from Dk
(State if wedges removed: no)
Sails: ✓
Equipment letter: C †
Anchors, No. of: 6
Cables (State if now ranged): no
" length (on board): ✓ size
" Rule length (per Table 22) size
Hawsers & Warps: good
Standing & Running Rigging: "

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of *ss No.* 1–98 and ptND98, &c.."

This vessel now appears to be in good & efficient condition & is eligible in my opinion to remain as classed, with record of survey 9.98, also the notation Ref. Mchy.

Office Fee (if chargeable) per Scale II., Sec. 27	£ : :	Fees applied for, ... 18	
Survey Fee (per Section 28)	£ : :		
Special Damage or Repair Fee (if any) (per Sec. 28.)	£ : :	Received by me, ... 18	
Travelling Expenses (if chargeable)	£ : :		
Second Surveyor's Fee (if any)	£ : :		

A C Campbell-Johns
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES. 13 SEP 1898

Character assigned 100A1 Ref. Mchy. 7 B.H.

HULL CERTIFICATE WRITTEN 27.2.99

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to

3481—5000.—4/98.—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Albers

© 2019 Lloyd's Register Foundation

LON716-0311