Rpt. 8. (Received at London Office WED. 28 SEP 1898) No. 602944

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report ..... 18 ..... When handed in at Local Office ..... 18 ..... Port of London

No. in Reg. Book. 827 Survey held at London Date, First Survey Aug 30 Last Survey Sept 14 1898 (No. of Visits five)

on the ~~Wood~~, ~~Iron~~ or Steel S.S. Bungaree Master

TONNAGE:— GROSS 2990 UNDER DK. 2761 NET 1875

Built at Newcastle By whom Wigham Richardson & Co When YEAR 1889 MONTH 9

Owners W. Lund. Port belonging to London

Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat & in Dry Dock? Name of Dock W. I. Graving Dk Destined Voyage Melbourne

WB=CellDBorDBa feet; uE&B feet; I feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59309 Port Lon

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1 3,98		+LMC. 10,97
88 no 2 9/.		

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition & damage (collision)

Condition

Vessel placed in dry dock, bottom sighted, cleaned & re coated.

Damage.

About 10 feet of angle iron in waterway abaft & renewed and anchor davit socket renewed. Rails & stanchions for about 20ft cut adrift, faired & replaced. Wood decks in way of damage recaulked., one waterway plate faired in place.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks: good
Caulking of Decks: "
Waterways: "
Coamings: "
Beams & Fastenings: "
Outside Plating: "
Caulking of ditto: "
Rivets: "
Breasthooks & Crutches: —
Transoms: —
Frames: gd.
Reverse Frames: "
Floors: —
Keelsons: —

Stringers: good.
Inner Bottom Plating: —
State if Tanks now tested: —
Bulkheads: gd
Ceiling: "
Cement or Asphalt (State which.): —
Rudder: gd.
Windlass: "
Have Pumps now been examined and found efficient?: —
Have Sluice Valves now been examined and found efficient?: —
Have Watertight Doors now been examined and found efficient?: —
Dblng. Plates under Sounding Pipes: —

Engine Room Skylights: good
Coal Bunkers, Open'gs, Lids, &c.: "
Scuppers: "
Cargo Hatchways.: "
Hatches: "
Planking of Wood Vessels
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto
Copper, or Y.M. (State if on Felt.) ditto
When put on, Month ..... Year .....

Boats: good.
Masts, Yards, &c.: "
Condition, how ascertained: deck
(State if wedges removed —)
Sails: —
Equipment letter: V
Anchors, No. of: 36, 15, 14.
Cables (State if now ranged):
" length (on board): not now ranged size
" Rule length (per Table 22): size
Hawsers & Warps: gd.
Standing & Running Rigging: —

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of *ss No.* 1–98 and ptND98, &c.."

This vessel appears to be in good condition & eligible in my opinion to remain as classed with fresh record of survey 9,98 Lon.

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	:
Survey Fee (per Section 28)	£	:	:
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees applied for, ... 18 .....
Received by me, ... 18 .....

A Martell.
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRI. 30 SEP 1898
Character assigned 100A1

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

3481—5000.—4/98.—Transfer Ink.

© 2019 Lloyd's Register Foundation

LON716-0375