COPY.

S.

12th. September, 1895.

Gentlemen,

With reference to Mr. Field's report No.7924 on the machinery of the steam tug "GWENNIE", I have to request he will state whether there is a doubling plate on the wide water space of the front tube plate as the thickness given on his report on the main boiler is only 9/16" with a pitch of 14" across the wide water space.

A prompt reply is requested and I have to add that to prevent unnecessary delay in future the drawings of boilers should be forwarded with your reports.

I am, Gentlemen,

Your obedient Servant,

Secretary.

The Surveyors,

L E I T H.

© 2019 Lloyd's Register Foundation

LTH565-0140