SS "Fifeshire" W. Hpl Report No. 6592

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 663

(Received at London Office) LLOYD'S REGISTER OF SHIPPING RECEIVED 11 MAY 87 LONDON

TESTS OF BOILER STEEL.

Tests of 2 Steel Plates manufactured by Teardale Iron & Coal Co of Spennymoor for Boiler No. 957 to be constructed by Blair & Co of Stockton for C. S. Swan & Hunters No. 105 Vessel

Date first visit 29.4.87 ~~last visit~~ No. of visits 1

The Plates specified in the accompanying copy of Advice Notes were rolled from 1 charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests were satisfactory.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions. Thickn. Ins.	Brdth. Ins.	Area. Ins.	Ultimate Stress. Total. Tons.	Sq. Inch Tons.	Exten. in 8 ins. %	Remarks.
	Back Tube		3262	9	.81	1.57	1.271	35.96	28.2	22	
	" "			" H	.80	"	1.256	35.49	28.2	22	

B.P. 14/5/87

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee ..... £ : :

Expenses £ : :

£ : :

Wm R. Austin

Surveyor, Lloyd's Register.

To be paid by West Hartlepool

[T. & Son—6000—5/5/85.]

NWC798-0094

© 2021 Lloyd's Register Foundation