The San Francisco Surveyors have been advised that the freeboards as recommended on the report are in order and that the vessel may be marked, the marks verified, and a provisional freeboard certificate issued.

breadth of vessel at the gunwale.

2 = ...

tm,9,20.

EEBOARD REPORT on the Mt. Sc. "Birkenhead"

It is submitted the Freeboards given on the accompanying form being those required by the Tables merit approval.

21. 6. 21.

© 2021 Lloyd's Register Foundation

W1006-0103

W1006-0105

at the

Poop.....

Total 194.00

Winter Freeboard from deck line ..... 7' 7¾