Register Tonnage as cut on Beam .. 2025

LENGTH on Deck as per Rule	Feet.	Inches.	BREADTH— Moulded	Feet.	Inches.	DEPTH, ACTUAL—Top of Floors to top of Upper Dk. Beams	Feet.	Inches.
	203	0		47	0		27	11¾

No. of Decks
No. of Tiers

Round of Dk. Beam

Inches. Size in Ship. | Inches. Spac Sh

Inches Ship. | Inches in Ship.

Cut to Cap

Long

57

× 5

24 to

71

× 5

24 to

Lloyd's Register Foundation

Jan. 14, 15.

1

Sent to Chief Surveyors 4.4.17

Received from Chief Surveyors

VESSEL'S NAME Steel screw schooner "Golden Evans" Report Ballinran No. 2033

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/02.)

Nature of Survey *When due*

RETAIN

✠ 100A1 (Steel) "Carrying petroleum in bulk"
2 Dks (Steel) & Web frames. "Longitudinal framing"
FP.T. 73 G. A.P.T. 117 G.
FK. 11 BH (7 BH to upper Dk 4 BH to 2nd Dk)
pl. cem. aver. P 76. F 26 Hardy abl.

5.4.17

W10/5-0024

Certificates for cast steel stemframe rudder should be forwarded for filing with 1st sub. report

Single Angle, Bulb } Angle, Plate, Tee Bulb, or Channel } In way of Long Bridge .....
" Spacing .....
BEAMS, Second Deck, Single Angle, Bulb }

" Deck.* Material and thickness
Fourth and Fifth Deck Stringer Plate, breadth & thickness }
" " " Angles on ditto, No.
" " " Tie Plates outside Hatchways

© 2020 Lloyd's Register Foundation