Christina Naudn

N.N. ~~SPRINGBAD~~ ~~TURYSHAND~~

F.E.

Received by Chief Ship Surveyor 15. 6. 09 *Received from Chief Ship Surveyor*

VESSEL'S NAME Str. S.S. "Shotton" Report Hull No. 21300

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	2/20"	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing:— Bulb angle framing as approved. (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") as recommended.

✠ 100 A 1 ("Steel")
1 DR (Stt) Well Deck.
W. B = FPT 40t
BK 7½" 3BH Cem. Lloyd's A & CP Q 48' B 11' F 23' Mdy Aft.

C. K. J. 15/6/09

© 2020 Lloyd's Register Foundation

W1015-0146