steamer "UALAN", being a survey for classification, we shall

19.

ived by Chief Ship Surveyor ..... Received from Chief Ship Surveyor .....

SSEL'S NAME STEEL S.S. "UALAN" Rpt. Cff No. 41734.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

ure of Survey First Entry.

Before this case receives the consideration of the Committee, the Surveyors should be requested to forward a sketch of Rudder shewing position of arms. They should also be requested to state whether the thickness of Keel is as per plan or as given on report. The thicknesses of Shell Plating at ends of vessel should also be given & it should be stated whether the sheerstrake is doubled or increased in thickness in way of Poop Front.

n 15/12/19.

15-12-19

© 2020 Lloyd's Register Foundation

W1031-010

Angle, Plate, Tee Bulb, or Channel
acing .....
d and Fourth Deck, Single Angle,
b Angle, Plate, Tee Bulb, or Channel
gles on upper edge .....

Poop Deck Stringer Plate, breadth & thickness 21"
,, Angle on ditto .....
,, Tie Plates .....