1m,8,21.

F.E.

Received by Chief Ship Surveyor ..... Received from Chief Ship Surveyor .....

VESSEL'S NAME Stl S M/V "SUMATRA" Rpt. Dr No. 7755

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

~~Transverse~~ 1st Long No. 14210 Depth "d" 23.5'

Framing: Table No. ✓ Description Channel & bulb angle frames

2nd Longitudinal No. 36063 as approved

Proportions $\frac{\text{Length}}{\text{Depth}}$ = 11.5

~~Deck~~ Sheerstrake as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A. 1. (Steel) "with freeboard," as recommended. The Summer freeboard of 11ft 1½in from centre of disc to top of statutory deck line at — deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dk (Stl), 3rd Dk (Stl) in No 1 Hold.

Coll D.B. 341' 1153t, D.T. a 33' 1037t, F.P.T. 208t, A.P.T. 121t.

F.K, 8 B.H. (Coll B.H. to Weather Dk), pt cem, Lloyds A. CP.

22/1/27

W1060-0241

© 2020 Lloyd's Register Foundation

" " " Flat Plate Keel Angles ✓ In No. 1 Hold Spacing .....

Side Keelsons. No. each side ✓