5m.10,47.

1

Sent to Chief Surveyors ..... *Received from Chief Surveyors* .....

VESSEL'S NAME ORDUNA. *REPORT* Liv. *No.* 131451.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey Screw shaft. *When due* P. 11,48, Centre 8,50 S. 12,51.

N O T E D.

Subject to the centre screw shaft liner being renewed before the end of 7,51 and to a new crankshaft being fitted to the emergency engine at the first opportunity but without special conditions regarding the port screw shaft.

21.9.50.

© 2021 Lloyd's Register Foundation

0100-0801M