Do. of excess of Hatchways
Do. above Crown of Engine Room .. 8·21
Gross Tonnage 162·42
Less Crew Space 13·28

Girth of Half Midship Frame (as per Rule) .....
1st Number ..... 41·67
Length on deck from after part of stem to fore part of 103·875

By whom built Messrs Smith
Owners De Bergvaschery M

Received by Chief Ship Surveyor 29. 6. 03

Received from Chief Ship Surveyor .....

VESSEL'S NAME Stt. Steam Trawler "Zeeleeuw" Report Nwc. No. 45475

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey First entry

It is submitted that before this case receives the consideration of the Committee, the Surveyors should be requested to state whether the hawsers required by Table 22 have been supplied, and if so, they should state their lengths and sizes as these particulars have been omitted from their report.

Lr to Nwc 29.6.03

C. H. J. 29/6/03

© 2020 Lloyd's Register Foundation

W1117-0009

2000-4-03.

,, Hold	,,	,,	2½		2½			Forecastle Deck Stringer Plate, brdth & thcknss
Quarter, 'tween Dks..								,, Angle on ditto