COPY.

Rpt. 12.

3m,2,25.

nt to Chief Surveyors _____ Received from Chief Surveyors _____

ESSEL'S NAME Stl Sc. M.V. "CITY OF STOCKHOLM" Report Gls No. HH971

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report* 24/5/92.)

ature of Survey 1st Entry When due Revised Rules

✠ 100 A.1. (Stel) "with freeboard"
2 dks (Stl)
Cell D.B 35ft 1234t, D.T. a 26' 1049t, F.P.T. 141t, A.P.T. 58t.
F.K, 1 intermediate B.H in fore hold dispensed with 6 B.H only.
pt Cem, Lloyds A + CP., F 40'.

9.9.25

W117 D105

© 2021 Lloyd's Register Foundation

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:— _____