N.B.—All alterations in the existing records of tanks should be inserted.

CHARACTER.
✠ for Special Survey.
Date of last Survey and of

1m,12,41.

1

Sent to Chief Surveyors ..... *Received from Chief Surveyors* 13 APR 1942

VESSEL'S NAME EMPIRE BIRCH *REPORT* Grk. *No.* 21791

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey DAMAGE ~~*When due*~~

Subject to permanent repairs to buckled shell plating, F.P. bulkhead and weather deck in way (p & s) at the first convenient opportunity.

© 2020 Lloyd's Register Foundation

W1185-0003

owing to the distortion of the fore end structure / the fore peak

SUMMARY OF DAMAGE REPAIRS :—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :—