Gross Tonnage ..... 122.58 | Length on Deck from after part of stem to fore part of stern post ..... 128-83 | Owners

Less Crew Space .....

F.E.

Received by Chief Ship Surveyor 12.1.05 *Received from Chief Ship Surveyor* .....

VESSEL'S NAME Stl. Stm. Trawler "Bassanio" Report Hul. No. 16517.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	As approved	
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Ordinary, as approved.	

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A1 ("Steel") "Stm Trawler" as recommended.

✠ 100 A1 ("Steel")
"Steam Trawler".
1 Dk.
BK 7". 4 BH. Cem. Lloyd's A & C P.
Q 5 F.

J. H. T.
12/1/05

© Lloyd's Register Foundation

5c,4,4.

W1217-0135

"	" Hold	"	"	2½	as per	Rule	2½	as per	Rule
"	Quarter, 'tween Dks.,	"	"	✓					

Forecastle Deck Stringer Plate, brdth & thckness
" Angle on ditto .....