71, Fenchurch Street, E.C. 3.

Mr. Wood

Rpt. 12.

29889.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port YOKOHAMA (When received in London Office) FRI. 15 APR. 1921

Vessel's Name "MANSHU MARU"

Official No. ~~149.~~ No. in Reg. Book

Port of Registry (For Foreign Vessels) DAIREN

Iron or Steel STEEL State whether Classed by Lloyd's Register CONTEMPLATED.

Name of Owners DAIREN KISEN KABUSHIKI KAISHA Date of Verification 17-2-1921.

29865. I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	5 ft.	8½ ins. ✓
From centre of disc to top of statutory deck line at awning or part-awning deck . . .	✓ ft.	✓ ins.
Fresh water line above centre of disc . . .		6 ins. ✓
Indian Summer line above centre of disc . .		5½ ins. ✓
Winter line below centre of disc		5 ins. ✓
~~Winter North Atlantic line below centre of disc~~		✓ ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of ~~wood or~~ iron deck with the vessel's side — at ~~main, spar or~~ upper dk.		1¾" ins. ✓
Steel — at awning or pt.-awning dk.		✓ ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

STATUTORY DECK LINE 1¾" ABOVE STEEL UPPER DECK AT SIDE.

James Crichton. Surveyor.

(To be filled up in London Office.)

Statement No. Date of Committee's Minute 19.4.21

Particulars for Record in Register Book.		
Moulded Depth . . .	30 ft.	0 ins.
Freeboard	5 ft.	8½ ins.
Corresponding Draught	24 ft.	8 ins.

Freeboards compared and found correct by GKM date 16.4.21

Is fee paid? New Form for Certificate A

Instructions date

Certificate written 18.4.21 Noted for posting JRB (Reprint)

1m,8,19.—T.

Winter Line below " " ... ...

~~Winter North Atlantic Line~~ " " " ... ...

* If the frames, skin planking, or ceiling are of unusual thickness ... of ceiling should be ...

© 2021 Lloyd's Register Foundation

W1313-0023