Cohen

W1359-0148

50.1.14.

Ursula Rickmers Whitmore

F.E.

Received by Chief Ship Surveyor 26.10.17 Received from Chief Ship Surveyor

VESSEL'S NAME Steeles Christlemore Rpt. Stpl No. 15417

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Transverse No. 8425 Depth "d" 18·33

Framing: Table No. 3. page Description Bulb Angles as approved

Longitudinal No. 35385

Shelter Proportions $\frac{\text{Length}}{\text{Depth}} =$ 10·7

Deck Sheerstrake as approved.

Cargo battens are not fitted in the Shelter tween decks owing the difficulty of obtaining wood at the present time

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A·1 (Shell) Shelter Deck with freeboard," as recommended. The Summer freeboard of 10' 0" from centre of disc to top of statutory deck line at Shelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

✠ 100 A·1 (Shell) Shelter Deck with freeboard

2 Dks (Steel) + Shelter Deck (Steel) 3 Dk Beams in No 1 Hold.

Cell O B 35' 1156 t. D.T. a 35' 954 t. F.P.T. 102 a P.T. 108 t

FK. 7 BH. Cem. Lloyds a+cP. F in Shelter Dk 34'

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

in Shelter tween Dks

26.10.17

BEAMS, Poop Deck, Angle, Bulb Angle, Plates, ~~T&~~ Bulb or Channel CHANNEL	12	4	·52	12	4	·52	" Tie Plates	

© 2020 Lloyd's Register Foundation