Rpt. 8. (Received at London Office WED. OCT. 30 1912) No. 31981.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 25 Oct. 1912 When handed in at Local Office 26. 10. 1912. Port of Glasgow

No. in Reg. Book. Survey held at Bowling Date, First Survey 23rd Oct. Last Survey 25th Oct 1912 (No. of Visits 2)

317 on the ~~Wood, Iron or~~ Steel S.S. "Agnes Ellen" Master Richardson

RETAIN

TONNAGE:— Built at Bowling By whom Scott & Sons When YEAR 1908 MONTH 12

GROSS 284 Owners J. H. Monks (Preston) Ld. Port belonging to Liverpool

UNDER DK. 224

NET 100 Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? On Slip Name of Dock Bowling Destined Voyage Coasting

WB=CellDBorDBa ... feet; uE&B ... feet; f ... feet; total capacity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

N.B.—All alterations in the existing records should be underlined.

...e vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ... examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ... of the inner bottom plating, especially in the boiler space.

Report, No. 27286 Port G.C.

...urveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...pairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ... of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ... being detailed in the body of the report, should be summarised in the form shown below. Whenever the ...t of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ... this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A1 12,08		+ LMC 12,08

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

...ases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were ...? ✓ Was a damage report made by anyone else? If so, by whom? ✓

...OR EXAMINATION AS PER RULE, FOR Docking.

...placed on slipway; bottom & rudder cleaned, examined, and ...ed; about 20 started rivets in keel & starboard strake in ...hold cut out and renewed; ceiling repaired & minor ...repairs.

...orecastle side plating and 2 frames in way of ram ...starbd side were found indented and a number of ...broken and seams started. The defective rivets (16) have ...cut out and bolts & grummets fitted & seams recaulked. Captain ...that the indented plating, frames & rivets wd be dealt with ...S.S. No 1 & this, in my opinion might be approved.

DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
... ...								
...and Faired or Repaired								
...Repaired in place								

...ITION OF THE	
...	Good
...s	"
...	"
...	"
...ngs	"
...	see above
...	Good
...	"
...tches	✓
...	✓
...	see above
...	Good
...	✓
...	✓

Stringers	✓
Inner Bottom Plating	✓
State if Tanks have been examined inside	✓
State if Tanks now tested	✓
Bulkheads	Good
Ceiling	"
Cement ~~or Asphalt~~ (State which.)	"
Rudder	"
Steering gear and its connections	"
Windlass	"
Have Pumps now been examined and found efficient?	✓
Have Sluice Valves now been examined and found efficient?	✓
Have Watertight Doors now been examined and found efficient?	✓

Dblng. Plates under Sounding Pipes	✓
Engine Room Skylights	Good
Coal Bunkers, Open'gs, Lids, &c.	"
Scuppers	"
Cargo Hatchways	"
Hatches	
Planking of Wood Vessels	
Caulking ditto	
Treenails ditto	
Breasthooks & Stemson ditto	
Transoms, Pointers, & Crutches ditto	
Timbers of Frame at openings ditto	
Ditto ditto at other places ditto	
Stringers, Clamps & Shelfs ditto	
Salting (State if examined.) ditto	

Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month ... Year	
Boats	Good
Masts, Yards, &c.	"
Condition, how ascertained	from dk.
(State if wedges removed)	No
Sails	✓
Equipment letter	e
Anchors, No. of	2B. 1S. 1K.
Cables (State if now ranged)	No
" length (on board)	✓ size
" Rule length	size
Hawser & Warps	stated sufficient
Standing & Running Rigging	Good

Observations, Opinion as to Class, Recommendation, &c. :—

...e clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ...y, thus for example:—"....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of ...0," or "to remain as classed and to have record of survey, 1,10, and the notations of *as No.* 1–10 and ptND10, &c."

...sel is eligible in my opinion to remain as classed, subject ...forecastle side plating & frames being dealt with at S.S. No 1 ...proposed; record of survey to be deferred.

Is Certificate required? If so, to be sent to

Survey Fee (per Section 28)	£	:	:
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees applied for, ... 19...

Received by me, ... 19...

W. Watt

Surveyor to Lloyd's Register of British & Foreign Shipping.

(The Surveyors are ... not to write on ...) 10m.11.—Transfe...

Committee's Minute GLASGOW 29 OCT. 1912

Character Assigned As now subject

TUE. DEC. 24. 1912 Deferred write Liv. L 24/12/12

TUE. MAY 6 — 1913 first class ... repaired ... RB Lr. Liv 65

Rpt. Liv. 28/4/13

W1363-0102

© 2021 Lloyd's Register Foundation