COPY.

5th September 1919.

Dear Sirs,

I am in receipt of your First Entry Report No. 8197 on the Steel Screw Steamer "NEW MEXICO", and with regard thereto I shall be glad if you will state if arms are fitted at and between rudder pintles in this vessel.

You should also state if the hand pumps fitted are in efficient working order, and whether the margin angles to tank top are 7 x 7 x .50 as in sister vessels or 7 x 7 x .45 as stated in your report.

I am, Dear Sirs,

Yours faithfully,

Assistant to the Secretary.

The Surveyors,

BELFAST.

© 2021 Lloyd's Register Foundation

W147-0092