Gross Tonnage 10894·93
Less Crew Space 700·39
Length on deck from after part of stem to fore part of stern-post 537·92

~~Plans in fixtures at end of alphabet.~~
~~Dbdass KFTGh~~

1

Received from Chief Surveyors

Sent to Chief Surveyors 18. 11. 08

VESSEL'S NAME Stt. Twin S.S. "Morea" Report Sl. No. 27199

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." —*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey First entry ~~When due~~

+ 100 A 1 ("Steel") "Spar deck".

2 DBs (Stt-WS N pt Tank) & Spar DB (Stt-Tank S) Oblq DB in No 1, 4, 5 & 7 holds (Stt in No. 5 & 7)

N.B = Cell DB a 97' u E & B 160' f 189' 1420 t FPT 66 t APT 61 t

FK & BK 3" 10 BH pt Cum. Lloyds A & CP P108' B277' F92'

C.E.J. 18/11/08

Yr Mans:

Kindly state the moulded depth for record in R.B. rooling. C.S.E.W. 1.12.08.

3 f - 3" as per report. Need to be Spar Dk.

G.H.M. 1.12.08

© 2021 Lloyd's Register Foundation

W1539-0003

PILLARS, In 'tween Deck, size and spacing 28 3⅛ 3⅛ 54 28 3⅛ 3⅛ 54
3 Rows " Hold " " 4½ 54 4½ 54
" Quarter, 'tween Dks. " " 2⅞ 3⅛ 3⅝ 54 2⅞ 3⅛ 3⅝ 54
" Angle on ditto
" Tie Plates Steel deck
" Deck. Material and thickness
* If Iron or Steel Deck, state if whole or part, and if wood