(Received at London Office THUR.OCT.29.1912 No. 8439

t. 8.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 26th Oct. 1912 When handed in at Local Office 28th Oct. 1912 Port of Southampton

No. in Reg. Book. Survey held at Southampton Date, First Survey and Last Survey 25th Oct. 1912 (No. of Visits)

5 Sup. on the ~~Wood, Iron or~~ Steel S. Hopper "No 63" ex J. Constant IV "Master

(J. Constant IV)

TONNAGE:— Built at Hull By whom Earle's Co Ltd. When (YEAR.) 1912. (MONTH.) J. Constant.

GROSS 475.

UNDER DK.

NET

Owners J. Constant Port belonging to London.

Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Town Quay Destined Voyage Local

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A.1.		

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Equipment.

This vessel has now been supplied with 75fms - 8" Manilla and 90fms - 6" manilla in order to complete her equipment.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired	✓	✓	✓	✓	✓	✓	✓	✓
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks
Caulking of Decks
Waterways
Coamings
Beams & Fastenings
Outside Plating
Caulking of ditto
Rivets
Breasthooks & Crutches
Transoms
Frames New vessel
Reverse Frames
Floors
Keelsons

Stringers
Inner Bottom Plating
State if Tanks have been examined inside
State if Tanks now tested.
Bulkheads
Ceiling
Cement or Asphalt (State which.)
Rudder
Steering gear and its connections
Windlass
Have Pumps now been examined and found efficient?
Have Sluice Valves now been examined and found efficient?
Have Watertight Doors now been examined and found efficient?

Dblng. Plates under Sounding Pipes
Engine Room Skylights
Coal Bunkers, Open'gs, Lids, &c.
Scuppers
Cargo Hatchways
Hatches
Planking of Wood Vessels
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto

Copper, or Y.M. of Wood Vessels (State if on Keel.)
When put on, Month Year
Boats
Masts, Yards, &c.
Condition, how ascertained (State if wedges removed)
Sails
Equipment letter
Anchors, No. of
Cables (State if now ranged)
„ length size
„ Rule length (on board) size
Hawser & Warps
Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of *ss No.* 1-11 and ptND11, &c."

The above is reported for the information of the Committee

Survey Fee (per Section 28) £ : ✓ :

Special Damage or Repair Fee (if any) (per Sec. 29) £ : :

Travelling Expenses (if chargeable) £ : :

Second Surveyor's Fee (if any) £ : :

Fees applied for, 19

Received by me, 19

R. Elliott

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute FRI. NOV. 1 - 1912

Character Assigned see Minute in F.E. report

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

10m.9.12.—Thunter Ltd.

If Certificate required? If so, to be sent to

© 2021 Lloyd's Register Foundation

W1551-169