Rpt. 8. (Received at London Office 16 DEC 1919) No. 82476

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 16 DEC 1919 19 When handed in at Local Office 16 DEC 19 19 Port of Ipswich

No. in Reg. Book. Survey held at Great Yarmouth, Date, First Survey 7-7-19 Last Survey 27-11-1919 (No. of Visits)

24108 on the ~~Wood, Iron or~~ Steel Sc. K. "R.R.S." Master

TONNAGE:— GROSS 159 UNDER DK. 152 73

Built at Selby By whom Cochrane Sons Ltd When 1913 - 5 (YEAR. MONTH.)

Owners R. Sutton. Port belonging to Yarmouth.

Owners' Address ✓ (if not already recorded in Appendix to Register Book).

...ed Afloat or in Dry Dock? Both. Name of Dock Fellows DK Destined Voyage Coasting.

...lDBorDBa ... feet; uE&B ... feet; f ... feet; ...acity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✱ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A.1 Steam Trawler 8-13		+L.M.C. 6-13

...ll alterations in the existing records should be underlined.

...vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ...examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ...of the inner bottom plating, especially in the boiler space.

...Report, No. 26364 Port Hull

...urveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...pairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ...of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ...being detailed in the body of the report, should be summarised in the form shown below. Whenever the ...of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ...this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

...ases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were ...Yes. (Admiralty survey) Was a damage report made by anyone else? If so, by whom? ✓

...OR EXAMINATION AS PER RULE, FOR S.S. No 1. + Damage repairs

...Vessel placed in dry dock, the bottom + rudder examined, cleaned ...coated.

...holds, fore peak tank, Engine + boiler spaces, bunkers, + crew ...ces cleared, examined + coated when necessary, ceiling lifted as per ...s + cement examined + tested. the deck masts, Latchways + hatches ex^d. ...ing gear, capstan, pumps, anchors + cables examined.

...ge repairs:- 2 shell plates on port bow, faired in place, the stem faired in place, 2 shell plates on port side in way of fish hold removed, faired + replaced, 2 plates on S. side, under flat of bottom in way of fish hold, faired in place, + 1 length of port bilge keel faired in place.

P.T.O.

DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
... ...	✓	✓	✓	✓	✓	✓	✓	Stem + bilge keel
...and Faired or Repaired	2	✓	✓	✓	✓	✓	✓	faired.
... Repaired in place	4	✓	✓	✓	✓	✓	✓	

...ITION OF THE Good
...s ... "
... "
... "
...gs ... "
... "
...tches ... "
... "
... "
... "
... "
... "
... "

Stringers Good
Inner Bottom Plating ✓
State if Tanks have been examined inside Yes
State if Tanks now tested Yes
Bulkheads Good
Ceiling "
Cement ~~or asphalt~~ (State which.) "
Rudder "
Steering gear and its connections "
~~Windlass~~ Capstan "
Have Pumps now been examined and found efficient? Yes
Have Sluice Valves now been examined and found efficient? ✓
Have Watertight Doors now been examined and found efficient? ✓

Dblng. Plates under Sounding Pipes Good
Engine Room Skylights "
Coal Bunkers, Open'gs, Lids, &c. "
Scuppers "
Cargo Hatchways "
Hatches "
Planking of Wood Vessels
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto

Copper, or Y.M. of Wood Vessels ✓ (State if on Felt.) When put on, Month ✓ Year ✓
Boats Good
Masts, ~~Yards~~, &c. "
Condition, how ascertained Ex^d aloft (State if wedges removed) Yes
Sails ✓
Equipment letter ✓
Anchors, No. of 3
Cables (State if now ranged) Yes 1⅝" bare
" length (on board) 45 size 1⅝"
" Rule length 45 90 size 1⅝"
Hawser & Warps Good
Standing & Running Rigging "

Observations, Opinion as to Class, Recommendation, &c.:—

...e clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ...r, thus for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of ...," or "to remain as classed and to have record of survey, 1,11, and the notations of *ss No.* 1–11 and ptND11, &c."

...e vessel now being converted for coasting purposes, the ...ove is submitted for the Information of the Committee.

...section 28) £ 1 : 10 : 0
...Repair Fee (if any) £ 1 : 1 : 0
...(if chargeable) £ 2 : 10 : 0
...Fee (if any) £ : :

Fees applied for, 16 DEC 1919 19
Received by me, 18-12 1919 19

A. E. Falminer & Robert Rae
Surveyor to Lloyd's Register of British & Foreign Shipping

TUE JAN 13 1920

(To Surveyor) Committee's Minute
Character Assigned ~~Expunge Class~~ ~~Cancel Red Line~~ Withdraw Class & record

L.O. 15/1/20 ...
...
...

The linings have been removed from the fish hold, + extra iron stanchions fitted at the sides ends of the hatchways.

The Vessel has been measured by the Board of Trade Surveyor, + a freeboard assigned, + the Vessel is now carrying general cargoes on the Coast.

A.R.F.

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

Number of Certificate.	Anchors.*	Weight, Ex. Stock.			Weight of Stock.			Test, per Certificate.				Weight Required by Table 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	If Patent state name of Patentee.		If Stockless, state Mechanical Tests.
	1st Bower ...																
	2nd "																
	3rd "																
	Collective Weight.																
	Stream																
	Kedge.....																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		Weight of Chain Cable.		Length and size per Table 30 or 31.		Description.	Makers of Cables.	When and where tested and Superintendent.
	Length.	Diam.	Statutory.	Breaking.	Supplied.	Per Table 30 or 31.	Length.	Diam.			
	Fathoms.	Ins.	Tons.	Tons.	Cwts. qrs. lbs.	Cwts. qrs. lbs.	Fathoms.	Ins.			
Iron Stream Chain or Steel Wire....											

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

© 2021 Lloyd's Register Foundation