Rpt. 8. DISCLASSED SECTION 95 No. DISCLASSED 24 (Received at London Office 8 JAN 1910) No. 4353.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 5th Janry 1910 When handed in at Local Office ..... 19..... Port of Southampton

No. in Reg. Book. Survey held at Southampton Date, First Survey Dec. 31st Last Survey Jan. 1st 1910 (No. of Visits 2.)

612 on the ~~Wood, Iron or~~ Steel Twin S.S. "Rohilla" Master J. Smith

TONNAGE:— GROSS 4365.87 UNDER DK. 5588 NET 4205 (3.21)

Built at Belfast By whom Harland & Wolff Ld. When YEAR. 1906 MONTH. 11

Owners British India Steam Nav. Co. Port belonging to Glasgow

Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Dry dk. Name of Dock No. 6 dry dk. Destined Voyage Karachi.

WB=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet; total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 7261 Port Lon.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1. 8.08		+L.M.C.11.06.

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ also whether any damage report was made, and, if so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repainting.

Vessel placed in dry dock - bottom cleaned, examined and repainted.

RETAIN

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired	✓	✓	✓	✓	✓	✓	✓	✓
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks Good; Caulking of Decks "; Waterways "; Coamings "; Beams & Fastenings "; Outside Plating "; Caulking of ditto "; Rivets "; Breasthooks & Crutches "; Transoms "; Frames "; Reverse Frames "; Floors "; Keelsons "

Stringers Good; Inner Bottom Plating Not exd.; State if Tanks have been examined inside No.; State if Tanks now tested No.; Bulkheads Good; Ceiling "; Cement ~~on Asphalt~~ (State which.) "; Rudder "; Steering gear and its connections "; Windlass "; Have Pumps now been examined and found efficient? Not exd.; Have Sluice Valves now been examined and found efficient? Not exd.; Have Watertight Doors now been examined and found efficient? Not exd.

Dblng. Plates under Sounding Pipes Good; Engine Room Skylights "; Coal Bunkers, Open'gs, Lids, &c. "; Scuppers "; Cargo Hatchways "; Hatches "; Planking of Wood Vessels ....; Caulking ditto ....; Treenails ditto ....; Breasthooks & Stemson ditto ....; Transoms, Pointers, & Crutches ditto ....; Timbers of Frame at openings ditto ....; Ditto ditto at other places ditto ....; Stringers, Clamps & Shelfs ditto ....; Salting ✓ (State if examined.) ditto ....

Copper, or Y.M. of Wood Vessels ✓ (State if on Felt.) When put on, Month ✓ Year ✓; Boats Good; Masts, Yards, &c. "; Condition, how ascertained From deck (State if wedges removed) No.; Sails Good; Equipment letter C7; Anchors, No. of 3B. 1S. 1K.; Cables (State if now ranged) No.; " length (on board) 300 fms size 2 7/16; " Rule length (per Table 23) 300 fms size 2 7/16; Hawser & Warps Good; Standing & Running Rigging "

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,07," or "to remain as classed and to have record of survey, 1,07, and the notations of *ss No.* 1–07 and ptND07, &c."

This vessel appears to be in a good and efficient condition and eligible, in my opinion, to remain as classed with date of survey 1.10.

Survey Fee (per Section 28) £ : :

Special Damage or Repair Fee (if any) (per Sec. 28) £ : :

Travelling Expenses (if chargeable) £ : :

Second Surveyor's Fee (if any) £ : :

Fees applied for, ... 19.....

Received by me, ... 19.....

R. Elliott

Surveyor to Lloyd's Register of British & Foreign Shipping.

FRI. 7 JAN 1910

Committee's Minute

Character Assigned 100A1 W.

Has a Survey also been held on the Machinery of the Ship? If so, is the Report still now, or when will it be sent?

Yes. 8.08

(The Surveyors are requested not to write on or below the space for Committee's Minute. 10m.8.—Typewriter Ink.)

In Certificate required? If so, to be sent to

© 2021 Lloyd's Register Foundation W1572-0053