Less Navigation Spaces ... Beam at side to top of keel ... Port belonging to

1m.12.15.

~~"Westcoates"~~ "Loch Moidart"

~~Fort Dunlop~~

F.E.

Received by Chief Ship Surveyor 22-3-18

Received from Chief Ship Surveyor

VESSEL'S NAME Steels James Wright Rpt. Shd. No. 30435

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Transverse No. 37.12 Depth "d" 12.16

Framing: Table No. 3 page 10 Description Single angle as approved

Longitudinal No. 5734

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.24$

~~Deck~~ Sheerstrake 62 Sq ins with inserts of 36 sq ins.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100A-1 (Shell) Steam Trawler, as recommended.

1 Dk (Shell)

BK 7½. 4BH. 1 cm. Lloyds area Q 78. F 19.

22. 3. 18

© 2021 Lloyd's Register Foundation

W1629.0204

BEAMS. Poop Deck, Angle, Bulb Angle, Plate, Tee Bulb, or Channel .....

„ Angles on upper edge .....

Bridge Deck Stringer Plate, br'dth & thickness

„ Angle on ditto.....