POSTPONED SURVEYS.

Case of the S.S. "INCHMAY" (B.C. Class)

62734 *in Reg. Bk.* *tons, Built* 1920 - 1 mo.

ssed *Owners*

Port of Registry

vey Due Special Survey, Type 4, due 8.45.
Load Line Certificate expired 28.4.49.

The Hong Kong Surveyors write they are advised by the Owners hat this vessel is now due to arrive at that port, and they regret hat owing to uncertain conditions, they are not in a position to etermine exactly what will be done regarding survey, and she will emain there pending a decision.

The Surveyors add that the "Inchmay" and "Inchkeith" will oin the several other Williamson vessels laid up at that port. he type of vessel, coupled with local conditions, would seem to reclude repair at this time.

nmittee's Minute FRI. 3 JUN 1949 to Lloyds 3/6

nsion Record in R.B. reprint
Laid up pending survey

© 2021
Lloyd's Register Foundation

10,48.

W1649-0016