Tonnage for Fees ... 2nd Number ... 5·7 (Where necessary to be entered) Residence

Less Engine Room ...

Forames

Received by Chief Ship Surveyor 17.5.06 Received from Chief Ship Surveyor

VESSEL'S NAME Lt. Steam Trawler "Aries" Rpt. Hull No. 17834

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	8/16" in lieu of 8/20"	Not required
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Ordinary, increased to compensate for minim of reverse frames.	

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") "Steam Trawler" as recommended.

DISCLASSED SECTION. No. 8

✠ 100 A 1 ("Steel") "Steam Trawler"

1 DR.

BK 7½" 4BH Cem. Lloyd's A&CP Q 73' F 21'

C. Hof 17/5/06

5c,5,5.

© 2019 Lloyd's Register Foundation

W1654-0093

" " in Hold " " Tie Plates Deck plated over