Rpt. 8. (Received at London Office -6 MAY 1931) No. 98613.

REPORT of SURVEY for REPAIRS, &c.

-2 MAY 1931 LIVERPOOL

Date of writing Report ..... 19.. When handed in at Local Office ..... 19.. Port of .....

No. in Reg. Book. 67816. Survey held at Liverpool Date, First Survey 22/4/31 Last Survey 2/5/ 1931 (No. of Visits 5.)

on the ~~Wood~~, ~~Iron or~~ Steel S. S. 'CITY OF HANKOW'

TONNAGE:— GROSS 7360 UNDER DK. 7109 NET 4735.

Built at W. Hartlepool By whom W. Gray & Co. Ltd. When YEAR 1915. MONTH 6.

Owners Montgomery & Workman (1920) Ltd. Owners' Address (if not already recorded in Appendix to Register Book).

Managers Stall Line Ltd. Port belonging to Liverpool

Surveyed Afloat ~~or in Dry Dock~~? Yes Name of Dock Sheerness Destined Voyage

WB=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet

total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 98529 Port Liv

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 100 A.1. 7.29.		✠ LMC 10.30
S.S. GLS. N 3.5.27.		M.S. 5.27.
		B.S. 6.29.
		C.L. 7.29.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he ...ed his services for this purpose and to whom and why they were declined .....

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

Was a damage report made by anyone else? If so, by whom?

...RS, OR EXAMINATION AS PER RULE, FOR Minor alterations in way of Deep Tank. + Pt SS No 1.

During both fitting of the Bauer-Wach Turbine (at a previous date) the space for loading cargo in the Deep Tank had been curtailed. To facilitate loading of cargo in the Deep Tank minor alteration have been carried out to the tunnel stiffs (which are fitted on the outside of the tunnel).

These alterations are efficient and the arrangement satisfactory. Deep Tank tested on completion of repairs.

Part Special Survey 2nd No 1:- Deep Tank examined internally + tested. To complete the S.S.:- All rule requirements to be carried out except the foregoing.

...Y OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
...newed								
...moved and Faired or Repaired		✓						
...ired or Repaired in place								

...CONDITION OF THE

...	Good.
...of Decks	"
...	"
...Fastenings	"
...lating	✓
...ks	✓
...	✓
...	Pt sun good.
...rames	"
...nals	✓
...es	✓
...	✓
...	✓
...	✓
...tom Plating	

State if Tanks have been examined inside	Deep Tank only.
State if Tanks now tested	Deep Tank only.
Bulkheads	Good.
Ceiling	"
Cement ~~or Asphalt~~ (State which.)	✓
Rudder	✓
Steering gear and its connections	Good.
Windlass	"
Have Pumps now been examined and found efficient?	✓
Have Sluice Valves now been examined and found efficient?	✓
Have Watertight Doors now been examined and found efficient?	✓
Have Ventilators and their Coamings been examined and found efficient?	Yes.

Dblng. Plates under Sounding Pipes	✓
Engine Room Skylights	Good.
~~Coal Bunkers~~, Open'gs, Lids, &c.	"
Scuppers	"
Cargo Hatchways	"
Hatches	"
Planking of Wood Vessels	
Caulking ditto	
Treenails ditto	
Breasthooks & Stemson ditto	
Transoms, Pointers, & Crutches ditto	
Timbers of Frame at openings ditto	
Ditto ditto at other places ditto	
Stringers, Clamps & Shelfs ditto	
Salting ditto (State if examined.)	

Copper, or Y.M. of Wood Vessels (State if on Felt).	✓
When put on, Month ..... Year	—
Boats	Good.
Masts, ~~Yards~~, &c.	"
Condition, how ascertained	from ab.
(State if wedges removed)	—
Sails	—
Equipment letter	—
Anchors, No. of	4
Cables (State if now ranged)	✓
" length (on board) ..... size	✓ —
" Rule length	— —
Hawser & Warps	Good
Standing and Running Rigging	"

...eral Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of *ss No.* 1–24 and ptND24, &c."

This vessel so far as seen is in good condition and eligible in our opinion to remain as classed without fresh record of survey. Notation of S.S. to be deferred until the survey has been completed.

...ee (per Section 29)	£	Alts. 3 3 0.
...Damage or Repair Fee (if any) (...r Sec. 29)	£	
...ng Expenses (if chargeable)	£	
Second Surveyor's Fee (if any)	£	

Fees applied for, -5 MAY 1931 19.. Received by me. 17.8.31 19..

Gw. L. Lyle. + H. Murray

Surveyor to Lloyd's Register of Shipping.

Committee's Minute, LIVERPOOL -5 MAY 1931 FRI. 21 AUG 1931 TUE. 15 NOV 1932

Character Assigned As now. FRI. 11 DEC 1931 TUE. 6 DEC 1932

Note pt SS No 1. FRI. 26 FEB 1932

(The Surveyors are requested ...)

Is Certificate required? If so, to be sent to

W238-0041

© 2020 Lloyd's Register Foundation