Built at Woolston, Southampton By whom built J. I. Thornycroft & Co Yard No.

Rpt. 7.

For the information of Surveyors and the Committee only.

Received at ..... Office, ... 19

Lloyd's Register of Shipping.

(Report on Machinery, No. 13966 Port Southampton

No. 19795 ENGINE FORGINGS ~~OR CASTINGS.~~

may be required.

I have to report that the Forgings ~~or Castings,~~ as herein described, manufactured by Messrs W. Lomas Ld of Halesowen for the ~~Engines~~ Order No. S.29/1098 being constructed by Messrs J. I. Thornycroft & Co Ld of Southampton for the Ship No. 1099 being built by (Annalbane) of

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to

on Forgings ~~or Castings.~~

Lloyd's No. 8578 J.P. 23/12/29.

J Pringle Sheffield 7/1/30.

	~~CRANK SHAFT.~~ 6 Loose Couplings. ~~FLYWHEEL SHAFT.~~	~~THRUST SHAFT.~~	~~INTERMEDIATE SHAFT.~~	~~TUBE SHAFT.~~ ~~SCREW SHAFT.~~
l*	Siemens Steel			
ade	Forged			
aled	Yes.			
ions, Forgings	✓			
, Castings ...	✓			
s on ection } ...	Rough Machined			
on Standard t Pieces.	767			
Test.— er square inch ...	31.2			
ion per cent 2" ...	34.0			
nding Test.— before fracture ...	180°.			
hen Inspected	21/12/29 to 23/12/29.			

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

if any chargeable) £ ✓ To be paid at ✓

f of wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.

© 2019 Lloyd's Register Foundation W307-0161

High Pressure Air Receivers, No. None. Cubic capacity of each ✓ Internal diameter ✓

Seamless, lap welded or riveted longitudinal joint ✓ Material ✓