ess Engine Room 87·05
ess Navigation Spaces 6·95

Proportions—*Breadths to Length* 4·2
Depths to Length—Main Deck to top of Keel 8·9

Residence Drummore
Port belonging to Stranraer

(2m,11,5.)

1.

Sent to Chief Surveyors 9. 1. 06 *Received from Chief Surveyors*

VESSEL'S NAME Ltt. S.S. "Hamilton" Report Gls. No. 23420

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey First entry ~~When due~~

+ 100 A 1 ("Steel")

1 Dk (Stl) Weld Deck

N.B = FPT 17t

BK 6" 3BH Cem. Lloyd's A & CP Q 30' B 7' F 14' Melly Aft.

C. M.
9/1/06

© 2019
Lloyd's Register Foundation

W419-0151

Angles on Upper Edge
Spacing
Angles on ditto, No.